

WEGA ENGINEERING PTE LTD

Blk 176 Sin Ming Drive #04-16 Sin Ming Autocare Singapore 575721

Tel: 6452 1493

Fax: 6452 9153

GST Reg: 19-9900741 / Z

Claim Ref:

AIG Asia Pacific Insurance Pte. Ltd
78 Shenton Way, #11-16 Singapore 079120

Date : 03.11.2020

Vehicle No : SLE7752Z
Chassis No : RU11111419
Make/Model : HONDA VEZEL
Year : 2016

171
NOT AUTHORIZED
Resurvey by paint
86620-90 *Selay*

S/N	Qty	Description	Cost	10%	Amount	
1	1pc	FRONT BONNET	\$ 280.00	\$ 308.00	✓ 380	
2	1pc	FRONT BONNET HIAGE LH	\$ 35.00	\$ 38.50	✓ 35	
3	1pc	FRONT BONNET HIAGE RH	\$ 35.00	\$ 38.50	✓ 35	
4	1pc	FRONT BONNET INSULATION	\$ 75.00	\$ 82.50	X	
5	1pc	FRONT BONNET RUBBER	\$ 18.00	\$ 19.80	✓ 75	
6	1pc	FRONT BONNET LOCK	\$ 75.00	\$ 82.50	✓ 220	
7	1pc	FRONT BUMPER	\$ 220.00	\$ 242.00	X	
8	1pc	FRONT BUMPER TOWING COVER	\$ 12.00	\$ 13.20	X	
9	1pc	FRONT BUMPER REINFORCEMENT	\$ 220.00	\$ 242.00	✓	
10	1pc	FRONT BUMPER REINFORCEMENT LH	\$ 15.00	\$ 18.00	✓	
11	1pc	FRONT BUMPER REINFORCEMENT RH	\$ 15.00	\$ 18.00	X	
12	1pc	FRONT BUMPER LOWER SKIRT	\$ 180.00	\$ 198.00	✓ 180	
13	1pc	FRONT BUMPER LOWER GRILLER	\$ 48.00	\$ 52.80	✓ 68	
14	8pc	FRONT BUMPER CLIPS	\$ 16.00	\$ 17.60	✓ 30	
15	1pc	FRONT FOG LAMP	\$ 145.00	\$ 159.50	X	
16	1pc	FRONT FOG LAMP COVER	\$ 18.00	\$ 19.80	X	
17	1pc	FRONT RADIATOR BASE	\$ 220.00	\$ 242.00	X	
18	1pc	FRONT RADIATOR OULER	\$ 170.00	\$ 187.00	X	
19	2pc	FRONT GRILLER RADIATOR (ENGINE)	\$ 48.00	\$ 52.80	✓ 480	
20	1pc	FRONT GRILLER EMBLEM " LOGO "	\$ 18.00	\$ 19.80	✓ 880	
21	1pc	FRONT HEADLAMP LH	\$ 680.00	\$ 748.00	X 880	
22	1pc	FRONT HEADLAMP RH	\$ 680.00	\$ 748.00	X 880	
23	1pc	FRONT HEADLAMP BRACKET LH	\$ 24.00	\$ 26.40	✓ 24	
24	1pc	FRONT HEADLAMP BRACKET RH	\$ 24.00	\$ 26.40	X	
25	1pc	FRONT SUPPORT PANAL	\$ 350.00	\$ 385.00	✓	
26	1pc	FRONT SUPPORT TOP GARNISH	\$ 48.00	\$ 52.80	X	
27	1pc	FRONT SUPPORT TOP BRACKET	\$ 48.00	\$ 52.80	✓ 48	
28	1pc	FRONT RADIATOR AIR DUCT RH	\$ 22.00	\$ 24.20	X	
29	1pc	FRONT RADIATOR AIR DUCT LH	\$ 22.00	\$ 24.20	X	
30	1pc	FRONT AIR COND	\$ 250.00	\$ 275.00	✓ 250	
31	1pc	FRONT RADIATOR	\$ 520.00	\$ 572.00	✓ 520	
32	1pc	FRONT FAN COWLING	\$ 66.00	\$ 72.60	X	
33	1pc	FRONT A/C FAN BLADE	\$ 45.00	\$ 49.50	X	
34	1pc	FRONT RADIATOR BLADE	\$ 45.00	\$ 49.50	X	
35	1pc	FRONT A/C FAN MOTOR	\$ 114.00	\$ 125.40	X	
36	1pc	FRONT RADIATOR FAN MOTOR	\$ 114.00	\$ 125.40	X	

Wega Engineering Pte. Ltd

Authorised Signature
Leong Chee Kwong
Mobile No: 84917768



CLAMP A FUEL HOSE 5.00 ✓ REC
CLIP - AMBIENT SENSOR BRACKET 15.00 ✓ REC
BONNET STONE CLIP 5 ✓ REC

LRK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

WEGA ENGINEERING PTE LTD

Blk 176 Sin Ming Drive #04-16 Sin Ming Autocare Singapore 575721
 Tel: 6452 1493 Fax: 6452 9153 GST Reg: 19-9900741 / Z

Claim Ref:

AIG Asia Pacific Insurance Pte. Ltd
 78 Shenton Way, #11-16 Singapore 079120

Date : 03.11.2020

Vehicle No : SLE7752Z
 Chassis No : RU11111419
 Make/Model : HONDA VEZEL
 Year :

S/N	Qty	Description	Unit Price	Amount
Parts Total				<u>\$ 5,409.50</u>

Labour Charges

1	To check wiring & system function	\$ 100.00	<i>20%</i>
2	To remove n refix radiator , aircond condensor n fan system	\$ 280.00	} <i>700%</i>
3	To vacuum & charge aircon R134 gas	\$ 60.00	
4	To inspect rear mechanisms & water test rear leaking	\$ 150.00	<i>nn</i>
5	To flushing & top up radiator water coolant	\$ 80.00	<i>50%</i>
6	To check headlamp lighting alignment	\$ 120.00	<i>Repair</i>
7	To replace , knocking accident front bonnet , bumper , support panel fender lh n rh	\$ 1,300.00	<i>x 60%</i>
8	To respray front portion, bonnet , bumper , support panel n fender lh & rh	\$ 1,000.00	<i>x 66%</i>

Grand Total

\$ 8,499.50

Wega Engineering Pte Ltd



Authorised Signature
 LIM HOCK GUAN
 Mobile No: 9833 2798