

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0832/2020/NS
DATE : 3-Nov-20
WIP : 56133

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MDM AZIZAH BINTI JAON
ADDRESS : BLK 535 PASIR RIS DRIVE 1
#02-284
SINGAPORE 510535
TELEPHONE : HP +65 96607736
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070139930
VEHICLE NO : **SLC 335 B**
MODEL CODE : AUDI Q3 SPORTSBACK 1.4 TFS
MODEL YEAR : 30/9/2020
ENGINE NO : CZD C05363
CHASSIS NO : WAUZZZF3XM1008431
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 31-Oct-20
PLACE OF ACCIDENT : TAKASHIMAYA BASEMENT 3 CARPARK EXIT



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLC 335 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY.	S/N \$ 400.00	X
2	TO REMOVE AND TRANSFER REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 280.00	✓
3	TO DISMANTLE AND RENEW RHS REAR DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	500
4	TO RESPRAY RHS FRONT DOOR, RHS REAR DOOR, DOOR COVERS AND RHS REAR WHEEL ARCH TRIM.	\$ 3,300.00	850 Door 550 Door Covers 200 Wheel Arch 200 850
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,372.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLC 335 B

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 REAR DOOR - RH <i>Defect</i>		\$	2,553.00 ✓	2042.40
2 REAR DOOR OUTER SEAL - RH <i>ren</i>	NEC	\$	134.00 ✓	106.80
3 REAR DOOR CATCH <i>Defect</i>		\$	119.00 ✓	94.80
4 SILL PANEL SEAL - RH <i>to Rte re.</i>		\$	134.00 X	
5 REAR DOOR COVER - RH <i>cut</i>		\$	345.00 ✓	276.00
6 FRONT DOOR COVER - RH <i>not re</i>		\$	366.00 X	
7 REAR WHEEL COVER - RH <i>cut</i>		\$	530.00 ✓	424.00
8 AUDI RING STICKER <i>ren</i>			TBC ✓	58.40
9 SUNDRIES <i>ren</i>		\$	300.00 ✓	9.20
TOTAL SPARE PARTS	:	\$	4,481.00	
TOTAL LABOUR CHARGES	:	\$	5,372.00	
GRAND TOTAL	:	\$	9,853.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE : *05/11/20*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT