

**BIKE PRODUCTION PTE LTD**  
610, Serangoon Road S(218216)  
Tel: 63922555, 62995177 Fax: 62975400  
ROC/ GST Reg No.: 200007407G

Date: 5 Nov 2020

ASSESSMENT FOR REPAIR: YAMAHA GDR155A (AEROX) - FBQ8256M

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front mudguard rear cover	\$75.00 / mis
1 pc	Front mudguard	\$95.00 / CRK
1 pc	Wheel axle	\$60.00 ?
1 pc	Brake disk	\$185.00 ?
1 pc	Right fork assy	\$420.00 ?
1 pc	Left fork assy	\$420.00 / SCR
1 pc	Steering stem	\$220.00 ?
2 pcs	Steering stem bearings @ \$45.00	\$90.00 ?
1 pc	Centre cover inner body	\$120.00 ?
1 pc	Centre cover lower	\$140.00 ?
1 pc	Front cover	\$95.00 / mis ?
1 pc	Headlamp lower cover	\$75.00 / mis
1 pc	Left front fairing	\$150.00 / SCR
1 pc	Left front fairing ambles	\$35.00 / SCR
1 pc	Left front fairing inner	\$35.00 ?
1 pc	Right front fairing	\$150.00 / mis
1 pc	Right front fairing ambles	\$35.00 / mis
1 pc	Right front fairing inner	\$35.00 / DEF
1 pc	Right floor step	\$105.00 / DEF
1 pc	Left floor step	\$105.00 / SCR
1 pc	Mainstand	\$195.00 / SCR
1 pc	Left engine cover	\$198.00 / SCR
1 pc	Left rear footrest	\$35.00 / SCR
1 pc	Left rear cover	\$145.00 / SCR
1 pc	Left rear cover ambler	\$35.00 / SCR
1 pc	Top cover front	\$95.00 ?
1 pc	Top cover front ambler	\$15.00 ?
		<hr/>
		\$3,363.00
Less discount 10%		<hr/>
		\$336.30
		<hr/>
		\$3,026.70
<b><u>Special nett items</u></b>		
1 pc	Front sport rim	\$420.00 X SCL
1)	Towing charges	\$100.00 X

2)	Replace, realign and adjust above damaged parts, check wiring and lighting system	<del>\$700.00</del> 300
3)	To remove, replace and balance front wheel rim	\$120.00 xnn
4)	To knock, straighten chassis & body balancing	\$380.00 xnn
5)	To remove/refit, replace (if damage) check and straighten front fork tubes.	\$180.00 ?
6)	Spray painting	<del>\$300.00</del> 100
<b>Total Estimate</b>		<u>\$5,226.70</u>

**Note: The above estimate is subjected to the prevailing GST of 7%**

N/A2 LXX



9/11/2020 1015

L15

3 DAYS

CHECK ITEM PHOTOS

AFTER REPAIR PHOTOS

  
  
For Bike Production Pte Ltd

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

Signature:

Date: