



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Ref: CS/GAI20012186/T1vd3e2 Date: 07/12/2021 Code: GAI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	YP 9452P	Veh. Inspected	FBL 2389D
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000003912	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	06/11/2020
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	YAMAHA SNIPER T150	c.c	150
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MH3UG0740G0023109	Colour	GREY
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	70/90 R17	MAXXIS	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/70 R17	MAXXIS	5 mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	01/11/2020	Inspection Date	06/11/2020
Survey held at	AUTOBOSS PTE LTD 1 SOON LEE STREET #03-33 PIONEER CENTRE SINGAPORE 627605		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	