



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI20006723/Eyd3e2-1

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 12-11-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 1216D	Veh. Inspected	SLE 7377Z
Policy No.	DMCVSNW00018152000	Coverage (\$)	0.00
Claim No.	SNM20D202244/C02/TANKL	Excess (\$)	0.00
Assign From	TAN KAH LEONG	Assign Date	09/11/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC 1.5 TURBO	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	MRHFC1660JT000035	Colour	WHITE
Odometer	36661	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/30 R19	YOKOHAMA	5 mm
L/H Front Tyre	255/30 R19	YOKOHAMA	5 mm
R/H Rear Tyre	255/30 R19	YOKOHAMA	5 mm
L/H Rear Tyre	255/30 R19	YOKOHAMA	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/06/2020	Inspection Date	26/06/2020
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	-----------------