



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

MR TAN JIA YONG KENNETH
BLK. 259C PUNGGOL FIELD
#06-47 SINGAPORE 823259

VEHICLE NO : SKZ 9085 D
MAKE/MODEL : HYUNDAI SONATA 2.0
DATE OF ACCIDENT : 07.11.20

SURVEY BY

THERE IS NO ESTIMATE. DUE TO THE DAMAGES SUSTAIN, IN OUR OPINION,
IT IS NOT ECONOMICAL TO THE REPAIR THE DAMAGE CAR AND IS
TO BE TREATED AS TOTAL LOSS.

WE NEED REPAIR THIS CAR AT

	S\$	25,000.00
GST 7%		1,750.00
	<u>S\$</u>	<u>26,750.00</u>

SIN DOLLARS: TWENTY-SIX THOUSAND SEVEN HUNDRED AND FIFTY ONLY

YOUR FAITHFULLY,


CYS AUTOMOBILE SERVICES PTE LTD