

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur

Date: 11 Nov 2020

**Preliminary Advice**

Vehicle No	: SLS7712R	Accident Date	: 09/11/2020
Make	: MITSUBISHI OUTLANDER	Policy No.	: 1700051656
Assignment Date	: 10/11/2020	Excess	: S\$600.00
Date of Inspection	: 10/11/2020	Est. Duration of Repair	: 10
Inspection At	: CYCLE & CARRIAGE AUTOMOTIVE PTE LTD (PANDAN GARDENS) 209 PANDAN GARDENS SINGAPORE 609339		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,661.35
Revised Amount	:S\$	11,700.54
Check Items (Estimated)	:S\$	2,751.21
Total	:S\$	14,451.75
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	83,000.00
COE / PARF Rebate	:S\$	51,555.00
Salvage Value	:S\$	
Margin for Repair	:S\$	31,445.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :