

ASS. REC. BY:

REF:

AIG/ 20012308/kb

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SDN 8988 B

Yr Regn:

10, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Veh/Kwogen

Sports van

7Si 1395

Colour

M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

81357

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WVW 888 AU 2 GW 52955

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

31/8/20

D.O.I.

25/11/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/12 112mp 81200k

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

: Parking

: Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S: AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

Estimate No: ES2000105

Date: 25 Nov 2020

Policy No:

Veh Reg No: SDN8988B

Make/Model: VOLKSWAGEN

SPORTSVAN 1.4 AT

AM13HZ CL

Chassis No: WVVZZZAUZGW529557

Engine No: CZC418573

Reg. Date: 14/10/2016

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 31/08/2020

TP Veh Reg No: SKF2868M

*Not Authorised
11/11/2020
Burning After Rain
2 days*

Estimate Repair Cost to Vehicle No :SDN8988B

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Spare Parts				
1 REAR BUMPER	1,450.50	1 PC	1,450.50	✓
2 REAR BUMPER SIDE RETAINER - LH	65.20	1 PC	65.20	X
3 REAR BUMPER SIDE RETAINER - RH	65.20	1 PC	65.20	X
4 REAR BUMPER REFLECTOR - RH	195.15	1 PC	195.15	X
5 REAR BUMPER LOWER PAD	285.10	1 PC	285.10	X
6 REAR BUMPER CLIPS	50.00	1 SET	50.00	✓
7 REAR BUMPER REINFORCEMENT	620.00	1 PC	620.00	X
8 REAR BUMPER TOWING COVER	60.00	1 PC	60.00	X
9 TAIL LAMP RH	585.50	1 PC	585.50	X
			3,376.65	3,376.65
Labour				
10 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	600.00	1 JOB	600.00	200/
11 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	600.00	1 JOB	600.00	220/
12 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	200.00	1 JOB	200.00	X
13 TO CHECK WIRING FUNCTIONS.	80.00	1 JOB	80.00	15/
			1,480.00	1,480.00

Total S\$ 4,856.65

Add GST @ 7% 339.97

Total Amount Payable S\$ 5,196.62

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND ONE HUNDRED NINETY SIX AND CENTS SIXTY TWO ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

[Handwritten Signature]