



CYCLE & CARRIAGE

AIG-OD (REVERT)
SURVEY: 10/11/20
LKL - RASUL.

VEHICLE NO : SMV6964J

MODEL : MIT/OUTLANDER 2.0 STYLE

WIP : 59420

Material	:	\$	<u>7,335.16</u>
Labour	:	\$	<u>5,730.00</u>
Sub-Total	:	\$	<u>13,065.16</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>13,065.16</u>
GST 7%	:	\$	<u>914.56</u>
Grand Total	:	\$	<u>13,979.72</u>

re- Finalise By/Date : Ammy on 28/12/20

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 13 WORKING DAYS + 4 days (Two wk. ends)

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 11/11/2020	Cust No/Name	KCV16151/TAN JUE LING, CHERYL
	Reg No/Reg Date	SMV6964J / 15/10/2020
	Date In/Mileage	10/11/2020/ 1003
	Chassis/Package	GF7W0700761 /DC17PT
	Engine No	4J11CQ4591
	Make/Model	MIT/20MY OUTLANDER 2.0 STYLE (999)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	28/12/2020/ 13:35	BLK	884 / Lauro Songcuan	59420

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR BUMPER, TAILGATE & AFFECTED AREAS				1350.00 ✓
E PNT98000 SPRAY PAINT ON REAR BUMPER, TAILGATE, END PANEL & REAR LH FENDER				1400.00 ✓
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST TO FACILITATE REPAIR				100.00 ✓
E PNT88000 REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR				240.00 ✓
M SUNDRY APPLY REAR WINDSCREEN SEALANT				80.00 ✓
E PNT88000 REMOVE & INSTALL REAR BOOT COMPARTMENT TO FACILITATE REPAIR				120.00 ✓
E PNT88000 TRANSFER TAILGATE ATTACHMENT TO NEW PANEL				80.00 ✓
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS				40.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
M SUNDRY SUPPLY C&C EMBLEM				40.00 ✓
E PNT88000 REPLACE FRONT BUMPER MIDDLE COVER				225.00 ✓
M SUNDRY SUNDRIES				30.00 ✓
S SPECIALISTJOB REPLACE FRONT NUMBER PLATE WITH FRAME				50.00 ✓
E PNT88000 REPLACE REAR END PANEL & REPAIR REAR FLOOR PANEL				675.00 X
E PNT98000 SPRAY PAINT REAR FLOOR PANEL				350.00 X

(450+225)

supp.

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 11/11/2020	<table> <tr> <td>Cust No/Name</td><td>KCV16151/TAN JUE LING, CHERYL</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMV6964J / 15/10/2020</td></tr> <tr> <td>Date In/Mileage</td><td>10/11/2020/ 1003</td></tr> <tr> <td>Chassis/Package</td><td>GF7W0700761 /DC17PT</td></tr> <tr> <td>Engine No</td><td>4J11CQ4591</td></tr> <tr> <td>Make/Model</td><td>MIT/20MY OUTLANDER 2.0 STYLE (999)</td></tr> <tr> <td>Colour/Trim</td><td>U01 TITANIUM GREY M/ BK BLACK</td></tr> </table>	Cust No/Name	KCV16151/TAN JUE LING, CHERYL	Reg No/Reg Date	SMV6964J / 15/10/2020	Date In/Mileage	10/11/2020/ 1003	Chassis/Package	GF7W0700761 /DC17PT	Engine No	4J11CQ4591	Make/Model	MIT/20MY OUTLANDER 2.0 STYLE (999)	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK
Cust No/Name	KCV16151/TAN JUE LING, CHERYL														
Reg No/Reg Date	SMV6964J / 15/10/2020														
Date In/Mileage	10/11/2020/ 1003														
Chassis/Package	GF7W0700761 /DC17PT														
Engine No	4J11CQ4591														
Make/Model	MIT/20MY OUTLANDER 2.0 STYLE (999)														
Colour/Trim	U01 TITANIUM GREY M/ BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	28/12/2020/ 13:35	BLK	884 / Lauro Songcuan	59420

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRONT BUMPER				225.00
E PNT98000 SPRAY PAINT FRONT BUMPER				350.00
A 15900099 REPLACE REAR EXHAUST MUFFLER & CENTER EXHAUST PIPE				225.00
X REFLECTOR, TAIL LAMP, LH	1.00	100.00	23.00	77.00
X EXTENSION, RR BUMPER	1.00	292.00	23.00	224.84
X FACE, RR BUMPER	1.00	807.00	23.00	621.39
X BRKT, R/BMPR FACE SIDE, RH	1.00	12.00	23.00	9.24
X PANEL, RR END	1.00	324.00	23.00	249.48
X DAM, TAILGATE SIDE	1.00	27.00	23.00	20.79
X FASTENER, WINDSHIELD	4.00	6.00	23.00	18.48
X DAM, TAILGATE, UPR	1.00	13.00	23.00	10.01
X STOPPER, WINDSHIELD GLASS	8.00	3.00	23.00	18.48
X MARK, OUTLANDER	1.00	95.00	23.00	73.15
X EXTENSION, FR BUMPER	1.00	515.00	23.00	396.55
X BUZZER, KEYLESS OPERATIO, RR	1.00	91.00	23.00	70.07
X ANT, KEYLESS OPERATION, RR	1.00	96.00	23.00	73.92
X REFLECTOR, TAIL LAMP, RH	1.00	100.00	23.00	77.00
X MOULDING, RR BUMPER, LH	1.00	88.00	23.00	67.76
X COVER, FR BUMPER	1.00	359.00	23.00	276.43
X FACE, FR BUMPER	1.00	859.00	23.00	661.43
X RIVET, FR BUMPER	10.00	5.00	23.00	38.50
X GARNISH, FR BUMPER SIDE	1.00	112.00	23.00	86.24
X PANEL ASSY, TAILGATE	1.00	984.00	23.00	757.68
X BRKT, R/BMPR FACE SIDE, LH	1.00	12.00	23.00	9.24
X DAM, TAILGATE, LWR	1.00	41.00	23.00	31.57
X MUFFLER, EXHAUST MAIN	1.00	579.00	23.00	445.83
X PIPE, EXHAUST, CTR	1.00	1814.00	23.00	1396.78
X GASKET, CATALYTIC CONVERTER	1.00	11.00	23.00	8.47
X REINFORCEMENT, RR BUMPER, LH	1.00	79.00	23.00	60.83
X BODY KIT, OUTLANDER	1.00	1554.00	00.00	1554.00



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



THIS IS NOT AN OFFICIAL TAX INVOICE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Parts	7,335.16		Nett	13,065.16
Labour	5,490.00	7% GST on	13065.16	914.56
Standard Menu	0.00			
Specialist Job	50.00		Total Payable	13,979.72
Diagnostics Job	0.00			
Sundry/Others	190.00			
Total(w/o GST)	13,065.16			

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : **AIG**

Supplementary For Registration No.: **SMV 6964 J**

	<u>Materials</u>	<u>Cost \$</u>
1	Buzzer, Keyless Operation, RR	91.00
2	Ant, Keyless Operation, RR	96.00
3	Moulding, RR Bumper, LH	88.00
4	Face, FR Bumper	859.00
5	Rivet, FR Bumper (10 pcs)	50.00
6	Garnish, FR Bumper Side	112.00
7	Panel Assy, Tailgate	984.00
8	Pipe, Exhaust, CTR	1,814.00
		<u>4,094.00</u>
	23% Discount	941.62
		<u>3,152.38</u>
9	Body Kit, Outlander	1,554.00
		<u>4,706.38</u>
	<u>Labour</u>	
1	Replace Rear End Panel & Repair Rear Floor Panel	675.00
2	Spray Paint Rear Floor Panel	350.00
3	Replace Front Bumper	225.00
4	Spray Paint Front Bumper	350.00
		<u>1,600.00</u>
	Labour & Materials	6,306.38
	7% GST	441.45
	Total	<u>6,747.83</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens