

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 14:20

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85016167 Date : 09/04/2021 Order : SMA9335R Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SMA9335R (V 37596) Regn Date: 22/06/2018 Mileage: 46813 WIP No.: 56908
Model: A3 SPORTSBACK 1.0 TFSI 8VFPANG Chassis: WAUZZZ8V5JA110102 Engine: CHZ 933727 Dept: U
You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: BNP - TO SUPPLY VEHICLE NUMBER PLATE	60.00	1.00	60.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNES FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	280.00	1.00	280.00
S	BODYWORK	M: TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNIT AND POWER MODULES	500.00	1.00	500.00
S	BODYWORK	M: TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS.	1200.00	1.00	1,200.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND LHS FRONT FENDER.TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	2750.00	1.00	2,750.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER,BONNET,HINGES AND BOTH FRONT FENDER.	2300.00	1.00	2,300.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8V0807065R GRU	COVER	Less 020%	1.00	1842.00
X	A8V3807647B 9B9	GRILLE (LAST)	Less 020%	1.00	158.50
X	A8V3853651AA3FZ	GRILLE	Less 020%	1.00	1406.00
X	A8V0010515A	STICKER	Less 020%	1.00	7.10
X	A8K0010520A	STICKER	Less 020%	1.00	13.50
					10.80

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 14:20

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice No: 85016167	Account: A0006 (T 0)
		Date : 09/04/2021	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
		Order : SMA9335R	
		Term : 30	
Regn No: SMA9335R (V 37596)	Regn Date: 22/06/2018	Mileage: 46813	WIP No.: 56908
Model: A3 SPORTSBACK 1.0 TFSI 8V FANG	Chassis: WAUZZZ8V5JA110102	Engine: CHZ 933727	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
X	A8V4807109E	BEAM	Less 020%	1.00	714.50
X	A8V0807550A	FOAM INSER	Less 020%	1.00	187.00
X	A8V0807217A	COVER	Less 020%	1.00	120.50
X	AN 0161857	POP-RIVET	Less 020%	10.00	3.20
X	A8V0823029D	HOOD (LAST)	Less 020%	1.00	2709.00
X	A8V0823301G	HINGE	Less 020%	1.00	60.30
X	A8V0823302G	HINGE	Less 020%	1.00	60.30
X	A8V0823126B	EDGING	Less 020%	1.00	27.30
X	A8V3854328C 01C	Strip (LAST)	Less 020%	1.00	66.00
X	A8V0805588A	CARRIER	Less 020%	1.00	719.00
X	AG A13040M2	COOLANT	Less 020%	4.00	22.60
X	A5Q0129254B	AIR DUCT	Less 020%	1.00	54.00
X	A8V3853949	PLATE AP	Less 020%	1.00	188.50
X	A8V3807233B	PLATE AP	Less 020%	1.00	293.00
X	A8V0121284K	AIR DUCT AP	Less 020%	1.00	24.00
X	A8V0121283K	AIR DUCT AP	Less 020%	1.00	24.00
X	A8V0121285A	AIR DUCT AP	Less 020%	1.00	11.70
X	A5Q0129954	COVER (LAST) AP	Less 020%	1.00	27.50
X	A5Q0121251HS	008513/ (V) (SK) RADIAT	Less 020%	1.00	859.00
X	A5Q0121251GD	RADIATOR (LAST) AP	Less 020%	1.00	941.00
X	A5Q0121367F	BRACKET AP	Less 020%	2.00	39.30
X	A5Q0816411BF	008513/ (V) (SK) CONDEN	Less 020%	1.00	516.50
X	A4D0260749B	WASHER AP	Less 020%	1.00	6.50
X	A3D0260749C	WASHER AP	Less 020%	1.00	8.40
X	A8V0941773D	HEADLIGHT AP	Less 020%	1.00	5455.00
X	A8V0821105L	FENDER (LAST)	Less 020%	1.00	841.00
X	A8V4823485C	HOOK AP	Less 020%	1.00	62.20
X	A8V2819401 9B9	COVER AP (LAST)	Less 020%	1.00	177.00

Parts 14,225.04
Labour 0.00
Sublet 7,282.00
Menus 0.00
Lubricant 0.00

Sub-Total 20,907.04

7% GST 1,463.49

Grand Total 22,370.53



Received by

For & on behalf of
Premium Automobiles Pte Ltd