

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
RAIMI
BIN ISNIN
655 SENJA ROAD
#10-278
Singapore 670655

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor
10-11-2020
5211043795
201009404M
30001
2020030105/ 1
10-11-2020
CHARMAINE KONG

License plate	Model code	First registration	VIN	Model	Mileage
SMG7084X	5C23EZ	28-12-2018	WVWZZZ16ZKM700992	Beetle 1.2 I TSI 77kW DSG	27,748

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Check Short Circuit / Harness Repair	1	pcs.	280.00 ✓	#1	280.00	299.60
	Diagnostic and Programming	1	pcs.	480.00 ✓	#1	480.00	513.60
5C5807417CBGRU	Cover For Bumper Primed (REAR)	1	pcs.	1,355.17 ✓	#1	1,355.17	1,450.03
5C5807305	Bumper (BUMPER REINFORCEMENT)	1	pcs.	496.43 ? Xnn	#1	496.43	531.18
5C5807861	Attachment Strip	1	pcs.	80.13 ✓	#1	80.13	85.74
5C5807393F	Guide Piece (BUMPER GUIDE LH)	1	pcs.	118.81 X nn	#1	118.81	127.13
5C5807394H	Guide Piece (BUMPER GUIDE RH)	1	pcs.	118.81 X nn	#1	118.81	127.13
5C5807131	Bracket (BUMPER BRACKET LH)	1	pcs.	45.11 ? Xnn	#1	45.11	48.27
5C5807132	Bracket (BUMPER BRACKET RH)	1	pcs.	45.11 ? Xnn	#1	45.11	48.27
5C5807568C 9B9	Air Vent Satin Black	1	pcs.	430.26 ? Xnn	#1	430.26	460.38
5C5853053 2ZZ	Decorative Moulding Chrom (RH LOWER CHROME MOULDING)	1	pcs.	117.21 ? Xnn	#1	117.21	125.41
5C5853054 2ZZ	Decorative Moulding Chrom (RH CHROME MOULDING)	1	pcs.	117.21 ? Xnn	#1	117.21	125.41
	LABOUR	1.8	pcs.	840.00	#1 840	2,520.00	2,696.40
	Spray Painting	1.8	pcs.	800.00	#1 800	2,400.00	2,568.00
	REAR NUMBER PLATE	1	pcs.	100.00 ✓	#1	100.00	107.00

Quotation valid till 17-11-2020

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	7,944.25	7%	609.30	8,704.25	9,313.55

Tanpin 97495774
wp' 13/11/20 21030.
Resurvey before paint
tanpin@lkkauto.com
03days

Service Advisor

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: