

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

10/11/2020

MS FIRST CAPITAL INSURANCE LIMITED

36 Robinson Road

#16-01 City House

Singapore 068877.

Page # :- 1

Veh # :- SDH9280J

Veh Model :- TOYOTA COROLLA 1.5M

Estimate# :- CK421192

Claim # :-

ACC. Date :- 05/11/20

Terms :- C.O.D Days

Remarks :-

Attention :- XA026

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1.	REAR BUMPER	1	PC	545.00	de	545.00
2.	REAR BUMPER SIDE RETAINER	2	PC	90.00	de	180.00
3.	REAR BUMPER ABSORBER BRACKET	2	PC	150.00	LH-RH	300.00 RHx
4.	REAR BUMPER CLIPS	10	PC	5.00	ne	50.00
5.	END PANEL GARNISH	1	PC	290.00	de	290.00
6.	END PANEL ASSY	1	PC	989.00	bt	989.00
7.	REAR FENDER LH	1	PC	1,780.00	bt	1,780.00
8.	REAR FENDER INNER SHIELD LH	1	PC	160.00	de	160.00
9.	TAILLAMP	2	PC	490.00	can	980.00
10.	REAR WINDSCREEN MOULDING	1	PC	210.00	ne	210.00
11.	BOOTLID	1	PC	890.00	bt	890.00
12.	BOOTLID LOCK	1	PC	340.00	?	340.00
13.	BOOTLID LOGO	1	PC	50.00	ne	50.00
14.	BOOTLID (XLI) EMBLEM	1	PC	50.00	ne	50.00
15.	BOOT LID (18I) EMBLEM	1	PC	50.00	ne	50.00
16.	BOOTLID (TOYOTA) EMBLEM	1	PC	50.00	ne	50.00
17.	BOOTLID (COROLLA) EMBLEM	1	PC	50.00	ne	50.00
18.	BOOTLID RUBBER	1	PC	230.00	ne	230.00
19.	BOOTLID HINGE LH	1	PC	160.00	?	160.00

LIST TOTAL S\$

7,354.00

25% DISCOUNT S\$

-1,838.50

5,515.50

SPECIAL NET ITEMS :

1.	REAR WINDSCREEN SEALANT	1	PC	40.00	ne	40.00
2.	REAR PARKING SENSOR	1	PC	200.00	mi's	200.00

SPECIAL NET TOTAL S\$

240.00

LABOUR :

TO INSPECT REAR LIGHTING WATER & LEAKAGE TEST

30 40.00

TO REMOVE & INSTALL REAR WINDSCREEN

✓ 120.00

TO REMOVE & INSTALL FUEL TANK

photo 60 80.00

TO REMOVE & INSTALL REAR COMPARTMENT
GARNISHES CARPET & ETC IN ORDER TO CUT OFF
END PANEL, LH REAR FENDER

60. 200.00

TO CUR OFF END PANEL, LH REAR FENDER &
STRAIGHTEN AFFECTED AREAS& RENEW DAMAGED PART

1200 1,400.00

TO APPLY BODY JOINT SEALANT ON CUTTING AREAS

✓ 40.00

TO APPLY RUST PROOF ON AFFECTED AREAS

50 100.00

TO SPRAY PAINT ON REPLACED, REPAIRED AREA

1200 1,200.00

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

10/11/2020

MS FIRST CAPITAL INSURANCE LIMITED

36 Robinson Road
#16-01 City House
Singapore 068877.

Page # :- 1 139478

Veh # :- SDH9280J

Veh Model :- TOYOTA COROLLA 1.5M

Estimate# :- CK421192

Claim # :-

ACC. Date :- 05/11/20

Terms :- C.O.D Days

Remarks :-

Attention :- XA026

No.	Description	Qty	U.Price	Amounts S\$
	LABOUR TOTAL S\$			3,180.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 8,935.50

GST @ 7 % 625.49

AMOUNT DUE S\$ 9,560.99

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Tanpin 77495749
WP 11/11/20 @ 330pm
Lumpsum
Resurvey after repair
Tanpin @ Handson.
8 days
* To check repair limit.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: