

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

10/11/2020

MS FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877.

Page # :- 1

Veh # :- SDH9280J

Veh Model :- TOYOTA COROLLA 1.5M

Estimate# :- CK421192

Claim # :-

ACC. Date :- 05/11/20

Terms :- C.O.D Days

Remarks :-

Attention :- XA026

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMPER	1 PC	545.00	545.00
2.	REAR BUMPER SIDE RETAINER	2 PC	90.00	180.00
3.	REAR BUMPER ABSORBER BRACKET	2 PC	150.00	300.00
4.	REAR BUMPER CLIPS	10 PC	5.00	50.00
5.	END PANEL GARNISH	1 PC	290.00	290.00
6.	END PANEL ASSY	1 PC	989.00	989.00
7.	REAR FENDER LH	1 PC	160.00	160.00
8.	REAR FENDER INNER SHIELD LH	1 PC	160.00	160.00
9.	TAILLAMP	2 PC	490.00	980.00
10.	REAR WINDSCREEN MOULDING	1 PC	210.00	210.00
11.	BOOTLID	1 PC	890.00	890.00
12.	BOOTLID LOCK	1 PC	340.00	340.00
13.	BOOTLID LOGO	1 PC	50.00	50.00
14.	BOOTLID (XLI) EMBLEM	1 PC	50.00	50.00
15.	BOOT LID (18I) EMBLEM	1 PC	50.00	50.00
16.	BOOTLID (TOYOTA) EMBLEM	1 PC	50.00	50.00
17.	BOOTLID (COROLLA) EMBLEM	1 PC	50.00	50.00
18.	BOOTLID RUBBER	1 PC	230.00	230.00
19.	BOOTLID HINGE LH	1 PC	160.00	160.00
LIST TOTAL S\$				7,354.00
25% DISCOUNT S\$				-1,838.50
				5,515.50
SPECIAL NET ITEMS :				
1.	REAR WINDSCREEN SEALANT	1 PC	40.00	40.00
2.	REAR PARKING SENSOR	1 PC	200.00	200.00
SPECIAL NET TOTAL S\$				240.00
LABOUR :				
TO INSPECT REAR LIGHTING WATER & LEAKAGE TEST				30 40.00
TO REMOVE & INSTALL REAR WINDSCREEN				120.00
TO REMOVE & INSTALL FUEL TANK				60 80.00
TO REMOVE & INSTALL REAR COMPARTMENT GARNISHES CARPET & ETC IN ORDER TO CUT OFF END PANEL, LH REAR FENDER				60 200.00
TO CUR OFF END PANEL, LH REAR FENDER & STRAIGHTEN AFFECTED AREAS& RENEW DAMAGED PART				1200 1,400.00
TO APPLY BODY JOINT SEALANT ON CUTTING AREAS				40.00
TO APPLY RUST PROOF ON AFFECTED AREAS				50 100.00
TO SPRAY PAINT ON REPLACED, REPAIRED AREA				2560 1,200.00

Spantype panel 4840 buc ✓ 7044.
25% 5283.

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

10/11/2020

MS FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877.

Page # :- 1 139478
Veh # :- SDH9280J
Veh Model :- TOYOTA COROLLA 1.5M
Estimate# :- CK421192
Claim # :-
ACC. Date :- 05/11/20
Terms :- C.O.D Days
Remarks :-

Attention :- XA026

No.	Description	Qty	U.Price	Amounts S\$
	LABOUR TOTAL S\$			3,180.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 8,935.50

GST @ 7 % 625.49

AMOUNT DUE S\$ 9,560.99

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Tanpin 77495749
WP 11/11/20 @ 330pm
Lumpsum
Resurvey after repair
Tanpin e/Handson.
10 & days
* To check repair limit.

5283

240

2560

8083

11/11/20 @ 330pm

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: