



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

-	Ref : CS/TP20012372/Uqf3e2
FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883	Date : 27-11-2020
ON BEHALF OF MUHAMMAD RASUL BIN HAZMAN Code : TP130	



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	FBD 156P
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	11/11/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA CB400	c.c	399
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	NC421003882	Colour	GREY
Odometer	-	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/70 ZR17	MICHELIN	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	180/55 ZR17	MICHELIN	5 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	07/11/2020	Inspection Date	11/11/2020
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------