

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/TP/0865/2020/NS
DATE	:	12-Nov-20
WIP	:	57308

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SKZ 2630 B

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR ZUTSHI ROHIT
ADDRESS	:	8 ALEXANDRA VIEW #10-08 SINGAPORE 158747
TELEPHONE	:	HP +65 96677054
TYPE OF CLAIM	:	THIRD PARTY CLAIM
POLICY NO	:	2100398711-05
VEHICLE NO	:	SFU 7643 S
MODEL CODE	:	AUDI Q3 1.4 TFSI S TRONIC
MODEL YEAR	:	15/1/2015
ENGINE NO	:	CHP 184567
CHASSIS NO	:	WAUZZZ8U5ER137122
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	10-Nov-20
PLACE OF ACCIDENT	:	TANGLIN TURNING TO ALEXANDRA RD SLIP ROAD

3456166

Cecilia

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFU 7643 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 280.00 ✓	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00 500	
3	TO RESPRAY REAR BUMPER.	\$ 1,000.00 550	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 2,672.00</u>	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFU 7643 S

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR BUMPER <i>Debond</i>		\$	1,379.00 ✓	1103.20
2	REAR BUMPER FIXING PARTS <i>new</i>		\$	123.00 x	
3	REAR BUMPER SPOILER <i>lit</i>		\$	470.00 ✓	376.00
4	REAR BUMPER CARRIER <i>new</i>		\$	617.00 +	
5	REAR PARKING AID SENSOR <i>new</i>	2	\$	500.00 +	
6	REAR WHEEL COVER - LH/RH <i>new</i>	2	\$	510.00 ✓	408.00
7	TAIL LIGHT - LH/RH <i>new</i>	2	\$	510.00 +	
8	SUNDRIES <i>new</i>		\$	200.00 x	46.96.
TOTAL SPARE PARTS		:	\$	4,309.00	
TOTAL LABOUR CHARGES		:	\$	2,672.00	
GRAND TOTAL		:	\$	6,981.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian L*
SURVEYED DATE : *18/11/20*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 days.*
H.S.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT