

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport:

Consistent? : Yes or No

G/A / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) __ S + RS, __ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

)

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

Not Authorized

12/11/20

3 days

take the other days



Service Centre

ESTIMATED COST: HQQ000420

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

SMJ121C
ANG KOK WEE ANDY
 BLK 112 BEDOK
 RESERVOIR ROAD
 #09-266
 SINGAPORE 470112
 CONTACT NO : 91479080

DATE : 12-NOV-2020
 MAKE : B.M.W.
 MODEL : 523I 2.5 AT ABS D/AB 2WD
 4DR GAS/D
 CHASSIS NO : WBAFP32010C257961
 ENGINE NO : 04807386N52B25AF
 SERVICE ADVISOR : GERINE
 PAGE : 1 OF 2

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LIST ITEM

1	REAR BUMPER <i>Dis ✓</i>	0.00	
1	REAR BUMPER RETAINER LH <i>11X</i>	0.00	
1	REAR BUMPER RETAINER RH <i>11X</i>	0.00	
1	REAR BUMPER SPONGE <i>NS X</i>	0.00	
1	REAR BUMPER CENTRE HOLDER <i>one ✓</i>	0.00	
1	REAR BUMPER REINFORCEMENT BEAM <i>Bar ✓</i>	0.00	
1	REAR BUMPER TOP COVER <i>11X</i>	0.00	
1	REAR BUMPER LOWER COVER <i>inner Kick plate one ✓</i>	0.00	
1	REAR BUMPER REFLECTOR LH <i>11X</i>	0.00	
1	REAR BUMPER REFLECTOR RH <i>11X</i>	0.00	
1	REAR BOOT LID RUBBER WEATHER STRIP <i>Two ✓</i>	0.00	
1	REAR BOOT LID INNER UPHOLSTERY TRIM <i>11X</i>	0.00	
1	REAR BOOT LID RUBBER GUARD STOPPER <i>11X</i>	0.00	
1	REAR FENDER LH <i>11X</i>	0.00	
1	REAR FENDER RH <i>11X</i>	0.00	
1	REAR FENDER NNER SHIELD LH <i>11X</i>	0.00	
1	REAR FENDER NNER SHIELD RH <i>11X</i>	0.00	
1	TAIL LAMP LH <i>11X</i>	0.00	
1	TAIL LAMP RH <i>11X</i>	0.00	
1	REAR END PANEL <i>R X</i>	0.00	
1	REAR END PANEL ANTENNA SENSOR <i>11X</i>	0.00	
1	TOWING COVER <i>11X</i>	0.00	
1	PARKING ASSIST MODULE <i>11X</i>	0.00	
1	REAR END PANEL INNER <i>R X</i>	0.00	
1	SMART OPENER SENSOR <i>11</i>	0.00	
1	EXTENTION PANEL <i>11X</i>	0.00	
1	SENSOR WIRE ASSY <i>11X</i>	0.00	

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4

#01-60 BARTLEY BIZ CENTRE SINGAPORE 417809

Tel: 67139400 Fax: 67139415

Email: servicecentre@abwinm9.com Website: www.abwinm9.com

Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000420**
TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

 DATE : 12-NOV-2020
 MAKE : B.M.W.
 MODEL : 523I 2.5 AT ABS D/AB 2WD
 4DR GAS/D
 CHASSIS NO : WBAFP32010C257961
 ENGINE NO : 04807386N52B25AF
 SERVICE ADVISOR : GERINE
 PAGE : 2 OF 2
SMJ121C**ANG KOK WEE ANDY**

BLK 112 BEDOK

RESERVOIR ROAD

#09-266

SINGAPORE 470112

CONTACT NO : 91479080

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	TAIL LAMP BRACKET LH <i>nx</i>	0.00	
1	TAIL LAMP BRACKET RH <i>nx</i>	0.00	
Sub Total		0.00	0.00

SPECIAL NETT

4	PARKING SENSORS <i>should</i>	1,520.00 <i>2pc's</i>	
10	FENDER CLIPS <i>nx</i>	50.00 <i>X</i>	
<i>1 set</i> 10	BUMPER CLIPS <i>see</i>	50.00 <i>/</i>	
Sub Total		1,620.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	800.00 <i>520</i>	
1	TO SPRAY PAINT ON AFFECTED AREAS	800.00 <i>680</i>	
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING	60.00 <i>20</i>	
1	TO REMOVE, REFIX/RENEW REVERSE CAMERA ASSY	100.00 <i>350</i>	
1	TO DIAGNOSE, REPLACE AND/OR TO RECTIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	200.00	
1	TO PROVIDE LABOUR, WORKSMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	<i>Repaired</i> 1,800.00 <i>X</i>	
Sub Total		3,760.00	0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

SUB-TOTAL**5,380.00****0.00****GST - 7 %****376.60****0.00****TOTAL****5,756.60****0.00****ABWIN SERVICE PTE LTD**

- Third party survey is on a "Without Prejudice" basis
- No major modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Prepared By _____

Date: _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	322G
Vehicle Details	
Vehicle No.:	SMJ121C
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Nov 2020
Vehicle Make:	B.M.W.
Vehicle Model:	523i 2.5 AT ABS D/AB 2WD 4DR GAS/D
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	04807386N52B25AF
Chassis No.:	WBAFP32010C257961
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$37,571.00
Original Registration Date:	28 Jul 2010
First Registration Date:	28 Jul 2010
Transfer Count:	3
Actual ARF Paid:	\$37,571.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jul 2030
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$33,568.00
COE Rebate Amount:	\$32,584.00
Total Rebate Amount:	\$32,584.00

The information contained herein is correct as at 12 Nov 2020

OK

The Useful Guide for Drivers

Useful resources when you are on the move.

[Carpark Rates](#) | [ERP Guide](#) | [Petrol Stations](#)

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

2017 Toyota Previa 2.4A Aeras Luxury @ \$103,800



Cheapest In The Market, 1

Owner, Very Low Mileage Done,

1.88%, 7 Seaters!

Hamilton Autohub StarAd

click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

Browse by Category

« Back (1 2 3) Next »

Sort by Date Posted 20 results/page

41 vehicles

bmw 523

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	bmw 523		Any	Any	2010	Any	Any	Any	Available
	BMW 5 Series 523i Highline Sunroof (New 10-yr COE)		\$72,800	\$7,280 /yr	09-Sep-2010	2,497 cc	109,000 km	Luxury	Available
2 YEARS WARRANTY, High Loan Available, 2 Years In-House Warranty Official Certificate, 2 Years Free Servicing And Maintenance, Acci...									
Carway									
Posted: 12-Nov-2020 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i									
	BMW 5 Series 523i Highline (COE till 05/2030)		\$72,800	\$7,640 /yr	24-May-2010	2,497 cc	167,000 km	Luxury	Available
High Spec Unit With Comfort Access, Auto Tailgate, Pedal Shifters And Drive Mode Selector! 100% Loan Available! Low Full Loan Interes...									
San Hup Bee (S) Pte Ltd									
Posted: 11-Nov-2020 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i									
	BMW 5 Series 523i (New 10-yr COE)		\$67,988	\$6,800 /yr	26-Nov-2010	2,497 cc	126,000 km	Luxury	Available
Superb Well Maintained By Previous Owner, COE Unit, Low Mileage, Flexible Loan Available With Low-Interest Rate, Trade-In Welcome,...									
Posted: 11-Nov-2020 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i									
	BMW 5 Series 523i (New 10-yr COE)		\$71,800	\$7,180 /yr	15-Dec-2010	2,497 cc	92,000 km	Luxury	Available
Most Wear And Tear Done Up By Meticulous Owner! Buy With A Peace Of Mind! VICOM/STA Welcome! 1 Year Free Warranty Package A...									
EDM Cars Pte Ltd									
Posted: 11-Nov-2020 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i									
Is your COE expiring? Let us help you renew it!									
Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.									
	BMW 5 Series 523i (New 10-yr COE)		\$69,800	\$6,980 /yr	08-Dec-2010	2,497 cc	98,000 km	Luxury	Available
Low Genuine Mileage! Full Loan Available At \$1092, 1 Year Free Servicing And Brand New Battery, In-house Warranty Provided, Vehicle...									
Precise Auto Trading Pte Ltd									
Posted: 10-Nov-2020 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i									
	BMW 5 Series 523i (New 10-yr COE)		\$73,800	\$7,380 /yr	29-Dec-2010	2,497 cc	108,000 km	Luxury	Available
Just Replaced 4 New Absorbers, Valve Cover Gasket, Gearbox Oil, Engine Oil, Filter And Plug.PQP Paid \$38216 Till 31/10/2030 Guarantee...									
Posted: 10-Nov-2020 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i									

Compare