

(08/11/13) wef  
ASS. REC. BY: *Marcus*

REF:

*CC4/AIG20012428/46a3*

### ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

*5*

days

Res.: Yes or No

Lum Sum:

*70*

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

*FBP 3671K*

Yr Regn:

*7 / 17*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

*Suzuki UH200A*

c.c

*200*

Colour

*Grey*

A/C:

Insured / Std / NI / NA

Sp. Reading

*Battery flap*

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

*MLCC91327140403762*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

*110/90-13*

R:

*130/70-12*

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

*6*

Rear

*6*

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

*1/11/20*

D.O.I.

*12/11/20*

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐


: Tech. Invs (\$

☐

: Weekend (\$

*26/12/20 H/S \$5700 confirmed with shuzi*

*LTA \$4080 MRP \$5728*



# 張 噴 漆 TEO SPRAY PAINTING

(INCORPORATED IN THE REPUBLIC OF SINGAPORE)  
Reg. Address: BLOCK 6, DEFU LANE 10, DEFU INDUSTRIAL PARK C, #01-558  
SINGAPORE 539187 TEL: 6283 5474 (2 LINES) FAX: 6287 2012  
REG. NO. 275084 / 00X

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way #07-16

Singapore 079120

Tel: 64193000

Fax: 68357416

Not Authorized  
marcus Lee  
12/11/20  
L/S # 5700 / limited  
Tel: 62563561  
Sdys.  
the phb After rep -

Dear Sir/Madam


09.11.2020

RE: THIRD PARTY CLAIMS FOR FBP3671K AGAINST YOUR  
INSURED SLS4476S, ACCIDENT ON 01.11.2020 AT  
KRANJI EXPRESSWAY

PG 1

| DESCRIPTION                                   | AMOUNT      |
|-----------------------------------------------|-------------|
| 1 FRONT FENDER <i>one</i>                     | \$ 145.00   |
| 2 FORK TUBE INNER (2 X \$185) <i>sent/one</i> | \$ 370.00   |
| 3 FORK OIL SEAL (2 X \$25) <i>one</i>         | \$ 50.00    |
| 4 FORK DUST SEAL (2 X \$28) <i>one</i>        | \$ 56.00    |
| 5 STEM STEERING <i>sent</i>                   | \$ 580.00   |
| 6 STEERING CONE <i>one</i>                    | \$ 120.00   |
| 7 HANDLE BAR <i>sent</i>                      | \$ 135.00   |
| 8 COVER HANDLE UPPER (BLACK) <i>one</i>       | \$ 85.00    |
| 9 COVER HANDLE LOWER (BLACK) <i>one</i>       | \$ 75.00    |
| 10 BALANCER <i>sent</i>                       | \$ 22.00    |
| 11 MIRROR ASSY RH <i>one</i>                  | \$ 60.00    |
| 12 MIRROR ASSY LH <i>one</i>                  | \$ 60.00    |
| 13 WINDSCREEN <i>one</i>                      | \$ 750.00   |
| 14 BRACE LEG SHIELD <i>one</i>                | \$ 145.00   |
| 15 PANEL METER LOWER (BLACK) <i>one</i>       | \$ 95.00    |
| 16 BOX FRONT (BLACK) <i>one</i>               | \$ 275.00   |
| 17 COVER FRONT <i>one</i>                     | \$ 140.00   |
| 18 EMBLEM "S" <i>one</i>                      | \$ 25.00    |
| 19 SHIELD LEG FRONT <i>one</i>                | \$ 320.00   |
| 20 SHIELD LEG LOWER <i>one</i>                | \$ 170.00   |
| 21 LAMP ASSY FRONT COMBINATION <i>one</i>     | \$ 380.00   |
| 22 FOOT BOARD FRONT (BLACK) <i>one</i>        | \$ 145.00   |
| 23 SHIELD LEG SIDE RH <i>one</i>              | \$ 155.00   |
| 24 SHIELD LEG SIDE LH <i>one</i>              | \$ 155.00   |
| 25 SHIELD LEG LOWER REAR (BLACK) <i>one</i>   | \$ 145.00   |
| 26 FOOT BOARD (BLACK) RH <i>one</i>           | \$ 35.00    |
| 27 FOOT BOARD (BLACK) LH <i>one</i>           | \$ 35.00    |
| 28 EMBLEM RH <i>one</i>                       | \$ 15.00    |
| 29 HANDLE PILLION RIDER RH <i>one</i>         | \$ 150.00   |
| 30 HANDLE PILLION RIDER LH <i>one</i>         | \$ 150.00   |
| 31 BODY MUFFLER <i>one</i>                    | \$ 1,300.00 |
| 32 COVER MUFFLER RR <i>one</i>                | \$ 85.00    |
| 33 COVER COMP MUFFLER <i>one</i>              | \$ 85.00    |





# 張 噴 漆 TEO SPRAY PAINTING

(INCORPORATED IN THE REPUBLIC OF SINGAPORE)  
Reg. Address: BLOCK 6, DEFU LANE 10, DEFU INDUSTRIAL PARK C, #01-558  
SINGAPORE 539187 TEL: 6283 5474 (2 LINES) FAX: 6287 2012  
REG. NO. 275084 / 00X

PG 2

|                                   |           |    |          |   |
|-----------------------------------|-----------|----|----------|---|
| 34 COVER MUFFLER                  | scr       | \$ | 85.00    | ✓ |
| 35 GUARD HEAT                     | 11        | \$ | 18.00    | X |
| 36 FRONT BRAKE LEVER              | scr       | \$ | 40.00    | ✓ |
| 37 LAMP ASSY FRONT TURN SIGNAL RH | cu        | \$ | 95.00    | ✓ |
| 38 LAMP ASSY FRONT TURN SIGNAL LH | cu        | \$ | 95.00    | ✓ |
| 39 REFLECTOR                      | cu        | \$ | 25.00    | ✓ |
| 40 DISC FRONT BRAKE               | scr       | \$ | 130.00   | ✓ |
| 41 AXLE FRONT                     | scr       | \$ | 35.00    | ✓ |
| 42 WHEEL FRONT                    | scr/waged | \$ | 650.00   | ✓ |
|                                   |           | \$ | 7,686.00 |   |
|                                   | Less 10%  | \$ | 768.60   |   |
|                                   | Sub Total | \$ | 6,917.40 |   |

PG 2

|                  |           |    |          |     |
|------------------|-----------|----|----------|-----|
| Nett Item        |           |    |          |     |
| 1 BOX 45L        | 11.5      | \$ | 150.00   | ✓   |
| 2 LABOUR CHAGRES |           | \$ | 280.00   | 250 |
| 3 FORK OIL       | 11        | \$ | 28.00    | ✓   |
| 4 TRANSPORT      |           | \$ | 70.00    | 35  |
|                  | Sub Total | \$ | 528.00   |     |
|                  | Total     | \$ | 7,445.40 |     |

THANKS  
TSP


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

7333

9-7613  
10%  
6851.70  
7386.70  
202  
5909.36



張 噴 漆  
**TEO SPRAY PAINTING**

(INCORPORATED IN THE REPUBLIC OF SINGAPORE)

Reg. Address: BLOCK 6, DEFU LANE 10, DEFU INDUSTRIAL PARK C, #01-556  
SINGAPORE 539187 TEL: 6283 5474 (2 LINES) FAX: 6287 2012  
REG NO. 275084 / 00X

Supplementary

|                     |      |           |              |
|---------------------|------|-----------|--------------|
| 1 REPAIR BODY FRAME | 11   | \$ 380.00 | X            |
| 2 RADIATOR          | sent | \$ 280.00 | ✓            |
| 3 FRONT TYRE        | cu7  | \$ 120.00 | 60% = 72 s/w |
|                     |      | \$ 780.00 |              |
| LESS 10%            |      | \$ 78.00  |              |
| Total               |      | \$ 702.00 |              |

Thank you.

Teo spray  
Shuqi