

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 17 Nov 2020

**Preliminary Advice**

Insured Vehicle No	: GBJ751P	Accident Date	: 08/11/2020
TP Vehicle No	: SLE4832X	Assignment Date	: 17/11/2020
Make	: TOYOTA AQUA HYBRID	Est. Duration of Repair	: 12
Date of Inspection	: 11/11/2020		
Inspection At	: OPTIMA WERKZ PTE LTD (HQ) 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-05 AMK AUTOPOINT SINGAPORE 568047		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,900.80
Revised Amount	:S\$	10,279.88
Check Items (Estimated)	:S\$	2,596.93
Total	:S\$	12,876.81
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :