SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties,
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	sent to the archiving of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	11/11/2020 09:40
Date Of Accident	11/11/2020 08:50
Exact Location Of Accident	KPE TUNNEL TWDS CITY (NEARBY AIRPORT ROAD EXIT)
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHC6517B
Insured/Policyholder	 Michiel Charles of the Administration of the Company of the Company
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	2XXXXX675H
Email Address	CLAIMS@PREMIERTAXI.COM
Mobile Phone No	
Alternative Phone No	OFFICE-62148880
Vehicle Particulars	智能是基础的重要的。
Manufacturer	HYUNDAI
Model	I30 (FD)-1.6 DOHC (A)
Exact Purpose for which vehicle was being used at time of accident	HIRED & REWARDS

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No. Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD Name of Insurance Company

THIRD PARTY Type Of Coverage

Fleet Policy YES

Policy Number 5107202885-01

Cover Note Number

Driver Control of the Control of the

Name of Driver LIM SZE GUAN (LIN SIYUAN)

NRIC No SXXXX359C Date Of Birth 09/04/1973 OUTDOOR Occupation Date Of Driving Pass 25/04/1991

Driving Experience 29 YEARS AND 6 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-91559060

Fax Number

Contact Number

EMail Address NOEMAIL Address BLK 271A #13-513
PUNGGOL WALK

Postcode 821271

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulańce?

NO YES

NO

2

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

citing/offering accident claims assistance.

Number of Passengers (Including Driver)
Passenger 1

NAME:

: PAX IN THE REAR SEAT - CHINESE

GENDER: : MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes,Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

VEH. A - 1 PAX VEH. B - 2-3 PAX

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLP4807L

Vehicle Make/Model/Colour KIA
Details Of Properties VEH. B

Vehicle Category PRIVATE CAR

Name of Driver BENJAMIN TAN WEI MING

NRIC/Passport Number SXXXX769F

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

Page 2 of 12

No. Of Passenger (Including Driver)

Sketch Plan Pq. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material
 facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:

Policyho der's Signati

Date & Time:

(i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

573)2359 C

(If driver is not the policyholder)

Date & Time:


Name: NRIC/FIN No.:

Reporting Centre Personnel's Signature

11 NOV 2020

× 11/11/2020

Sketch Plan Pg. 2



Sketch Plan Pg. 3

Describe Circumstance of the Accident.

ON 11/11/2020 @0850HRS, I WAS DRIVING MY TAXI (SHC 6517 B), TRAVELLING ALONG KPE TUNNEL TOWARDS CITY WITH A PASSENGER ONBOARD – ON LANE 2.


WHILE I WAS MOVING STRAIGHT AHEAD – SUDDENLY I FELT AN IMPACT FROM MY RIGHT.

WHEN INSPECTED, I DISCOVERED THAT VEHICLE B (SLP 4807 L - KIA) WHICH WAS INITIALLY ON LANE 1 - FAILED TO KEEP FOR PROPER LOOK OUT, HAD ENCROACHED ONTO MY PATH ON MY RIGHT ABRUPTLY & COLLIDED ONTO THE RIGHT PORTION OF MY TAXI.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE RIGHT PORTION & VEHICLE B HAD DAMAGES ON THE LEFT PORTION.

NO INJURY INVOLVED.

VEHICLE B HAD 2-3 PASSENGERS ONBOARD.



Text size +

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company Cert

No.:

200304975H

110..

Owner ID Type:

Company

Owner Name:

PREMIER TAXIS PTE, LTD.

Registered Address:

23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443

Mailing Address:

Birth Date:

Vehicle Particulars

Vehicle No.:

SHC6517B

Previous Vehicle No.:

-

Effective Date of Ownership: Original Regn Date: 16 Aug 2017 16 Aug 2017

_

40.4

Registration Date:

16 Aug 2017

Year of Manufacture:

2016

Vehicle Type:

Public Transport Taxi (Motor Car)

Vehicle Scheme:

Taxi (Company)

Vehicle Attachment 1:

Air-Con (Taxi)

Vehicle Attachment 2:

Vehicle Attachment 3:

-

Vehicle Make:

HYUNDAI

Vehicle Model:

130 GDH 1.6 TCI 5DR DCT

Primary Colour:

Silver

Secondary Colour:

-

Passenger Capacity:

4

Chassis No.:

TMAD281UVHJ134086

Engine No.:

D4FBGZ144482

Engine Capacity/Power

1582 cc / -

Rating: Maximum Power Output:

100.0 kW (134 bhp)

Propellant:

Diesel

Max Unladen Weight:

1496 kg

Maximum Laden Weight:

1940 kg

Open Market Value:

\$20,278.00

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

15 Aug 2025

Minimum PARF Benefit:

\$7,734.00

No. of Transfers:

0

IU Label No.:

1050706862

COE No.:

2017081601003878D

COE Expiry Date:

15 Aug 2025

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Registration Category:

A - Car up to 1600cc & 97kW (130bhp)

Quota Premium (QP) / Prevailing Quota Premium:

-/\$45,400,00

PQP Paid:

.

QP (Regn Cat):

\$36,320.00

ar (Rogn Car).

OPC Cash Rebate Eligibility: No

https://vrl.lta.gov.sg/lta/vrl/action/menuIndex

1/2

11/11/2020 Invoice



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No:

GR-20-139317

Date of Request:

11/11/2020

Your Ref No:

Online Purchase

Premier Automotive Services Pte Ltd

23 Changi South Ave 2

#01-02

Singapore 486443

Dear Sir/Madam,

Enquiry Date

11/11/2020

Enquiry By

LIEW HAI LEONG

TP Vehicle No.

SLP4807L

Accident Date

11/11/2020

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLP4807L	AIG Asia Pacific Insurance Pte, Ltd.	29/11/2019-28/11/2020	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No:

GR-20-139317

Date of Request:

11/11/2020

Your Ref No:

Online Purchase

Premier Automotive Services Pte Ltd 23 Changi South Ave 2

#01-02

Singapore 486443

Dear Sir/Madam,

Enquiry Date

11/11/2020

Enquiry By

LIEW HAI LEONG

TP Vehicle No.

SLP4807L

Accident Date 11/11/2020

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You,

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

11-Nov-20

ESTIMATE REPAIR BILL FOR HYUNDAI 130 (A) REGN NO: SHC 6517 B

1 pc	Front n/s door		\$ 1,723.60
1 pc	Support panel		\$ 1,243.60
1 pc	Delta garnish front o/s		\$ 15.30
1 pc	Mud guard front o/s		\$ 47.48
1 pc	Front o/s fender signal light @ \$32.10		\$ 32.10
1 pc	Washer tank motor		\$ 75.00
1 pc	Washer tank		\$ 51.40
1 pc	Front bumper o/s upper bracket		\$ 92.60
1 pc	Front bumper o/s support bracket		\$ 37.01
1 pc	Front o/s fog lamp cover		\$ 25.00
1 pc	Front o/s head lamp		\$ 1,531.57
1 pc	Front bumper		\$ 811.11
1 pc	Front bumper emblem		\$ 27.80
1 pc	Front bumper o/s side bracket		\$ 32.51
1 pc	Front o/s fender		\$ 514.02
1 pc	Front o/s rim		\$ 246.00
1 pc	Front o/s lower arm		\$ 811.34
1 pc	Front o/s shock absorber		\$ 611.56
1 pc	Front o/s tie rod end		\$ 72.50
1 pc	Front o/s ball joint		\$ 91.90
1 pc	Front o/s kunckle bearing		\$ 349.60
1 pc	Front o/s stabilizer link		\$ 88.50
1 pc	o/s mirror Assy		\$ 749.49
1 pc	Front o/s fender inner shield		\$ 176.72
			\$ 6,427.73
		Less 20%	\$ 1,285.55
			\$ 5,142.18

ESTIMATE REPAIR BILL FOR HYUNDAI 130 (A) REGN NO: SHC 6517 B

1 set Front bumper clips \$ 48.00 1 pc Front o/s fender sticker \$ 30.00 1 set o/s door sticker \$ 100.00 1 pc Tyre front o/s \$ 200.00 1 set Front o/s fender inner shield clips \$ 28.00 Sundry \$ 50.00 Towing Fee \$ 50.00 To check wheel alignment \$ 80.00 To focus/check front n/s & o/s head lamps \$ 60.00 To dismantle and refit the inner components of the front n/s door into new shell door \$ 150.00 To dismantle and replace the front o/s undercarriage \$ 250.00 To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. \$ 180.00 To abour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s door etc \$ 1,000.00 To putty and spray painting on front bumper, front o/s fender, front o/s door, front o/s wheel house, rear o/s door, o/s rocker panel \$ 1,200.00 To apply rustproofing on the repaired and replaced panels. \$ 150.00	S/NETT	<u> </u>	
1 set o/s door sticker \$ 100.00 1 pc Tyre front o/s \$ 200.00 1 set Front o/s fender inner shield clips \$ 28.00 Sundry \$ 50.00 Towing Fee \$ 50.00 To check wheel alignment \$ 80.00 To focus/check front n/s & o/s head lamps \$ 60.00 To dismantle and refit the inner components of the front n/s door into new shell door \$ 150.00 To dismantle and replace the front o/s undercarriage \$ 250.00 To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. \$ 180.00 To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s door etc \$ 1,000.00 To putty and spray painting on front bumper, front o/s fender, front o/s door, front o/s wheel house, rear o/s door, o/s rocker panel \$ 1,200.00 To apply rustproofing on the repaired and replaced panels. \$ 150.00	1 set	Front bumper clips	\$ 48.00
Tyre front o/s 1 set Front o/s fender inner shield clips Sundry Sundry Towing Fee To check wheel alignment To focus/check front n/s & o/s head lamps To dismantle and refit the inner components of the front n/s door into new shell door To dismantle and replace the front o/s undercarriage To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s door etc To putty and spray painting on front bumper, front o/s fender, front o/s door, front o/s wheel house, rear o/s door, o/s rocker panel To apply rustproofing on the repaired and replaced panels. \$ 150.00	1 pc	Front o/s fender sticker	\$ 30.00
Sundry Towing Fee Soundry To check wheel alignment Soundry To dismantle and refit the inner components of the front n/s door into new shell door To dismantle and replace the front o/s undercarriage To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s door, etc To putty and spray painting on front bumper, front o/s fender, front o/s door, front o/s wheel house, rear o/s door, o/s rocker panel To apply rustproofing on the repaired and replaced panels. \$ 150.00	1 set	o/s door sticker	\$ 100.00
Sundry Towing Fee \$ 50.00 To check wheel alignment \$ 80.00 To focus/check front n/s & o/s head lamps \$ 60.00 To dismantle and refit the inner components of the front n/s door into new shell door \$ 150.00 To dismantle and replace the front o/s undercarriage \$ 250.00 To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. \$ 180.00 To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s door etc To putty and spray painting on front bumper, front o/s fender, front o/s door, front o/s wheel house, rear o/s door, o/s rocker panel \$ 1,200.00 To apply rustproofing on the repaired and replaced panels. \$ 150.00	1 pc	Tyre front o/s	\$ 200.00
Towing Fee \$ 50.00 To check wheel alignment \$ 80.00 To focus/check front n/s & o/s head lamps \$ 60.00 To dismantle and refit the inner components of the front n/s door into new shell door \$ 150.00 To dismantle and replace the front o/s undercarriage \$ 250.00 To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. \$ 180.00 To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s door etc \$ 1,000.00 To putty and spray painting on front bumper, front o/s fender, front o/s door, front o/s wheel house, rear o/s door, o/s rocker panel \$ 1,200.00 To apply rustproofing on the repaired and replaced panels. \$ 150.00	1 set	Front o/s fender inner shield clips	\$ 28.00
To check wheel alignment \$80.00 To focus/check front n/s & o/s head lamps \$60.00 To dismantle and refit the inner components of the front n/s door into new shell door \$150.00 To dismantle and replace the front o/s undercarriage \$250.00 To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. \$180.00 To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s door etc \$1,000.00 To putty and spray painting on front bumper, front o/s fender, front o/s door, front o/s wheel house, rear o/s door, o/s rocker panel \$1,200.00 To apply rustproofing on the repaired and replaced panels. \$150.00		Sundry	\$ 50.00
To focus/check front n/s & o/s head lamps To dismantle and refit the inner components of the front n/s door into new shell door To dismantle and replace the front o/s undercarriage \$ 250.00 To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. \$ 180.00 To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s door etc To putty and spray painting on front bumper, front o/s fender, front o/s door, front o/s wheel house, rear o/s door, o/s rocker panel To apply rustproofing on the repaired and replaced panels. \$ 150.00		Towing Fee	\$ 50.00
To dismantle and refit the inner components of the front n/s door into new shell door \$ 150.00 To dismantle and replace the front o/s undercarriage \$ 250.00 To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. \$ 180.00 To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s door etc \$ 1,000.00 To putty and spray painting on front bumper, front o/s fender, front o/s door, front o/s wheel house, rear o/s door, o/s rocker panel \$ 1,200.00 To apply rustproofing on the repaired and replaced panels. \$ 150.00		To check wheel alignment	\$ 80.00
door into new shell door To dismantle and replace the front o/s undercarriage \$ 250.00 To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. \$ 180.00 To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s door etc To putty and spray painting on front bumper, front o/s fender, front o/s door, front o/s wheel house, rear o/s door, o/s rocker panel To apply rustproofing on the repaired and replaced panels. \$ 150.00		To focus/check front n/s & o/s head lamps	\$ 60.00
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s door etc To putty and spray painting on front bumper, front o/s fender, front o/s door, front o/s wheel house, rear o/s door, o/s rocker panel To apply rustproofing on the repaired and replaced panels. \$ 180.00		· ·	\$ 150.00
trims, cushion seat, carpet, etc to facilitate repairs. \$ 180.00 To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s door etc \$ 1,000.00 To putty and spray painting on front bumper, front o/s fender, front o/s door, front o/s wheel house, rear o/s door, o/s rocker panel \$ 1,200.00 To apply rustproofing on the repaired and replaced panels. \$ 150.00		To dismantle and replace the front o/s undercarriage	\$ 250.00
damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s door etc \$1,000.00 To putty and spray painting on front bumper, front o/s fender, front o/s door, front o/s wheel house, rear o/s door, o/s rocker panel \$1,200.00 To apply rustproofing on the repaired and replaced panels. \$150.00			\$ 180.00
To apply rustproofing on the repaired and replaced panels. \$ 150.00		damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s door etc To putty and spray painting on front bumper, front o/s fender, front o/s door, front o/s wheel house, rear o/s door, o/s	\$ ·
		rocker panel	\$ 1,200.00
\$ 8,718.18		To apply rustproofing on the repaired and replaced panels.	\$ 150.00
			\$ 8,718.18

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.