

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	12 Nov 2020 17:11	Clm Veh Model Changed	(202779) MITSUBISHI OUTLANDER 2.0 (A).	[] Merimen Administrator
2	12 Nov 2020 17:11	Clm Created	Reg No: SMN6276D. Policy No: 1900149638. Acct Date: 2020/11/12. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MCC620100390	[I] Merimen Administrator
3	13 Nov 2020 10:34	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] LEE SU THING
4	13 Nov 2020 10:34	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] LEE SU THING
5	13 Nov 2020 10:34	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] LEE SU THING
6	13 Nov 2020 10:34	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/11/24	[A] LEE SU THING
7	13 Nov 2020 10:34	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] LEE SU THING
8	13 Nov 2020 10:34	Clm Registration Modified	Rep:1137->200066.	[A] LEE SU THING
9	13 Nov 2020 10:34	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] LEE SU THING
10	13 Nov 2020 14:14	Clm Registration Modified	Acct Time:12:10:00->12:00:00. Init.Est.:->5,000 - 6,000. Excess: -> 300.00. Excess Waived: -> 30 0.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Azlan, Syazairdina
11	13 Nov 2020 14:14	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
12	16 Nov 2020 11:11	Adj Rpt Initiated		[A] HUEY YON
13	16 Nov 2020 11:11	Clm Dtl Modified	JPJ Reg. Date: -> 2019/08/22.	[A] HUEY YON
14	16 Nov 2020 11:11	Clm Details Notified		[A] HUEY YON
15	16 Nov 2020 12:09	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2020/11/24	[A] DENISE TAY KWEE CHENG
16	16 Nov 2020 12:13	Adj Mandate Request	Cur.Req:11569.05:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
17	16 Nov 2020 14:07	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/11/24. Mandate Remarks: Re-inspection require on hidden part, check item, supplementary part with clear photo. Note: Before painting photo require IF replace (headlamp panel)	[I] Chang, Lois-KL
18	16 Nov 2020 14:07	Adj Mandate Set	Approved:8867.00:Re-inspection require on hidden part, check item, supplementary part with clear photo. Note: Before painting photo require IF replace (headlamp panel)Reinsp:Yes.	[I] Chang, Lois-KL

Date From



Date To



Audit Type

None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2637717	16 Nov 2020 11:11:31	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SMN6276D		11.00

