



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref : S0M02X0Q Date: 10th Dec 2021

Our Ref : CC4/ASM20012527/Bps3q2

M/s AXA Insurance Pte Ltd

8 Shenton Way #24-01 AXA Tower Singapore 068811 (The Motor Claims Department)

Attn: CHAN KIAN CHUAN

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE GBC 7460U INSURED VEHICLE YQ 1894U ACCIDENT ON 05/11/2020

Instruction was received to inspect the vehicle Reg. No. GBC 7460U. The inspection was conducted on 16/11/2020 at the premises of M/s Team Autopro Pte Ltd, 160 Sin Ming Drive #01-14 Sin Ming Autocity, Singapore 575722.

The following vehicle information was recorded:

Registration Number : GBC 7460U

Make/Model : TOYOTA DYNA 150 MANUAL

Year of Registration : 2013 Body Colour : SILVER

Chassis Number : JTFAT35Y10K202417

Engine Capacity : 2982 cc

Speedometer Reading : -

The vehicle sustained damages at the front portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as "**uneconomical Total Loss**".

Market Value S\$ 32,500.00 (est)

Less: LTA Reimbursement Value (RV) (S\$ 19,215.00)

Nett Liability S\$ 13,285.00

Vehicle Inspected By:

LIM TEOW GUAN Automotive Assessor

K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK),

MASME(USA), B Bus(Aust), MBA(UK),

IEng(UK), MIIE(mech), MinstAEA, MFIEA,

MIRTE, MIMI, MSAE, MCIArd, AM, NIJAAR (USA),

AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.