

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 9 Feb 2021

SUPPL FOR REPAIR: HONDA CB400 - FBK5719X

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front left signal	\$125.00 / DEF
1 pc	Meter bracket	\$175.00 / BT
1 pc	Right switch assy	\$215.00 / DEF
1 pc	Right engine cover	\$395.00 / GRAZED
1 pc	Right engine cover gasket	\$65.00 / NEL
1 pc	Rear right tail cover	\$295.00 / SCR
1 pc	Right side cover	\$145.00
1 pc	Rear right footrest	\$95.00 / SCR
		<hr/>
		\$1,510.00
	Less discount 10%	\$151.00
		<hr/>
		\$1,359.00
	<u>Special nett items</u>	
1)	Labour for dismantle and fixing of suppl items	\$100.00 / SO
	Total Estimate	<hr/>
		\$1,459.00

Note: The above estimate is subjected to the prevailing GST of 7%



For Bike Production Pte Ltd