

Car-in 1/12/2020
wp: 57580

Kiam/Hong

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



Veron

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKG 39981

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1 FRONT BUMPER <i>Distorted</i>	\$	5,789.00 ✓	
2 FRONT BUMPER FIXING PARTS <i>new</i>	\$	258.00 +	
3 FRONT BUMPER CARRIER <i>new</i>	\$	1,145.00 +	
4 FRONT BUMPER SHOCK ABSORBER - LH <i>new</i>	\$	342.00 x.	
5 FRONT BUMPER GUIDE SECTION - LH/RH <i>LH RH</i>	\$	624.00 312	
6 RADIATOR GRILLE <i>cracked</i>	\$	4,201.00 ✓	
7 RADIATOR GRILLE CLOSING ELEMENT ?	\$	647.00 ?	
8 R53 INSCRIPTION <i>new</i>	\$	122.00 ✓	
9 FRONT BUMPER AIR GUIDE GRILLE - LH/RH <i>new</i> 2	\$	832.00 +	
10 FRONT BUMPER END CAP ?	\$	268.00 ?	
11 FRONT BUMPER TRIM STRIPS - LH/RH <i>new</i> 2	\$	850.00 ?	
12 FRONT BUMPER SPOILER - LOWER CENTRE <i>new</i>	\$	1,411.00 +	
13 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE ?	\$	397.00 ?	
14 FRONT BUMPER FOAM FILLER PIECE <i>new</i>	\$	268.00 +	
15 SPRING SHACKLE <i>new</i>	\$	66.00 +	
16 SIGNAL HORN - LOW/HIGH TONE <i>new</i> 2	\$	446.00 +	
17 FRONT FENDER - LH/RH <i>Distorted</i> 2	\$	12,602.00 ✓	
18 FRONT FENDER BRACE - LH FRONT <i>Best</i>	\$	53.00 ✓	
19 FRONT FENDER BRACKET - LH/RH LOWER <i>new</i> 2	\$	162.00 ✓	
20 FRONT FENDER CLOSING ELEMENT - LH/RH <i>new</i> 2	\$	184.00 ✓	
SUB TOTAL SPARE PARTS <i>RH.</i> :	\$	30,667.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKG 39981

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 WHEEL HOUSING LINER - LH/RH INNER <i>RA torn LH torn</i>	2	\$ 586.00	293 586 ✓
22 WHEEL HOUSING LINER - LH/RH OUTER <i>RA torn</i>	2	\$ 586.00	293.
23 WHEEL SPOILER - LH/RH <i>LH torn</i>	2	\$ 134.00	67.
24 WHEEL HOUSING SOUND ABSORBER - LH/RH ?	2	\$ 212.00	?
25 BONNET		\$ 2,373.00	+
26 BONNET LID HINGE - LH/RH	2	\$ 114.00	+
27 BONNET CATCH HOOK		\$ 92.00	+
28 BONNET LID LOCK		\$ 212.00	+
29 BONNET LOCK COVER - UPPER FRONT <i>new</i>		\$ 51.00	+
30 HEADLIGHT - LH/RH <i>LH could</i>	2	\$ 4,556.00	2278
31 GAS DISCHARGE LAMP		\$ 408.00	+
32 GAS DISCHARGE LAMP CONTROL UNIT <i>new</i>		\$ 1,084.00	+
33 CORNERING LIGHT POWER MODULE		\$ 1,043.00	+
34 HEADLIGHT HOSE - LH <i>new</i>		\$ 12.00	+
35 FLAT CONTACT HOUSING <i>new could</i>		\$ 30.00	✓
36 LIFT CYLINDER - LH <i>new could</i>		\$ 201.00	✓
37 LIFT CYLINDER HOSE <i>new</i>	5	\$ 184.00	+
38 WASH WATER RESERVOIR <i>new</i>		\$ 170.00	+
39 LOCK CARRIER ?		\$ 2,289.00	?
40 AIRCON CONDENSER <i>not in</i>		\$ 1,079.00	X
SUB TOTAL SPARE PARTS		\$ 15,416.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKG 3998 J

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	AIRCON STICKER <i>new</i>	NEC	\$	18.00	✓
42	ADDITIONAL RADIATOR <i>new</i>		\$	1,874.00	+
43	ADDITIONAL RADIATOR BRACKET - LH RH <i>1/2</i>	2	\$	426.00	+
44	READY MIX COOLANT <i>?</i>		\$	91.00	?
45	RADIATOR AIR GUIDE - LH <i>?</i>		\$	39.00	?
46	RADIATOR AIR GUIDE - LH OUTER <i>?</i>		\$	78.00	?
47	FRONT DOOR - RH <i>Distorted</i>		\$	2,176.00	✓
48	FRONT DOOR HINGE - RH LOWER <i>Dist.</i>		\$	237.00	✓
49	FRONT DOOR HINGE - RH UPPER <i>?</i>		\$	71.00	?
50	DOOR HINGE RETAINING PLATE <i>?</i>		\$	13.00	?
51	FRONT DOOR SIDE REINFORCEMENT <i>?</i>		\$	157.00	?
52	FRONT DOOR INNER SEAL <i>new</i>		\$	250.00	✓
53	TYRE PRESSURE DATA PLATE <i>new</i>		\$	20.00	✓
54	EXTERIOR MIRROR MOUNTING - RH <i>?</i>		\$	1,013.00	?
55	MIRROR CAP - RH <i>Dist.</i>		\$	1,282.00	✓
56	MIRROR GLASS - RH <i>new</i>		\$	1,644.00	+
57	TURN SIGNAL INDICATOR <i>new</i>		\$	99.00	+
58	FRONT DOOR COVER - RH <i>Distorted</i>		\$	326.00	✓
59	FRONT DOOR PROTECTIVE STRIP - RH <i>Distorted</i>		\$	201.00	✓
60	SIDE MEMBER TRIM - RH <i>Distorted</i>		\$	1,029.00	✓
SUB TOTAL SPARE PARTS		:	\$	11,044.00	

KIV →

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKG 3998 J

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
61 SIDE MEMBER TRIM CAP - RH ? <i>Missing</i>		\$ 164.00	✓
62 A-PILLAR - RH <i>Dish'd</i>		\$ 1,120.00	✓
63 SILL TRIM STRIP - RH OUTER ?		\$ 679.00	?
64 SILL TRIM STRIP - RH INNER ?		\$ 187.00	?
65 DATA TAG ?		\$ 457.00	?
66 NOISE INSULATION ?		\$ 746.00	?
67 UNDERBODY TRIM ?		\$ 245.00	?
68 FRONT ALUMINIUM RIM - LH/RH <i>lit</i>	2	\$ 2,728.00	✓
69 TRACK CONTROL ARM - LH ?		\$ 371.00	?
70 WHEEL BEARING HOUSING - LH ?		\$ 666.00	?
71 WHEEL BEARING ?		\$ 949.00	?
72 GUIDE JOINT - LH ?		\$ 136.00	?
73 TIE ROD END - LH ?		\$ 122.00	?
74 STONE CHIP ?	S/N	\$ 180.00	?
75 CAVITY WAX ?	S/N	\$ 140.00	?
76 ACRYLIC SEALANT ?	S/N	\$ 180.00	?
77 FRONT NO PLATE <i>per</i>	S/N	\$ 60.00	✓
78 SUNDRIES ?		\$ 400.00	?
TOTAL SPARE PARTS	:	\$ 66,657.00	
TOTAL LABOUR CHARGES	:	\$ 30,484.00	
GRAND TOTAL	:	\$ 97,141.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

Add

8PO 805 607 A

Adnan Lj
03/12/20
Resigned.
H.S.