Ass. HEG. BY

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	537C
Vehicle No.:	SKG3998J
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Nov 2020
Vehicle Make:	AUDI
Vehicle Model:	RS3 SPORTBACK 2.5 TFSI QUATTRO
Primary Colour:	Grey
Manufacturing Year:	2012
Engine No.:	CEP010983
Chassis No.:	WUAZZZ8P5D1900009
Maximum Power Output:	250.0 kW (335 bhp)
Open Market Value:	\$55,482.00
Original Registration Date:	29 Aug 2012
First Registration Date:	29 Aug 2012
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$55,482.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Aug 2022
PARF Rebate Amount: Intended COE Rebate Details	\$30,515.00
COE Expiry Date:	28 Aug 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$82,289.00
COE Rebate Amount:	\$14,666.00
Total Rebate Amount:	\$45,181.00
ne information contained herein is correct as at 16 Nov 20	020

The information contained herein is correct as at 16 Nov 2020

SGCARMART.COM

Login Sign up

Forum

New Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Resources



CONNECTING CAR BUYERS & SELLERS. We'll handle your loans, insurance & other paperwork for FREE.



Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

Citroen C4 Picasso 1.6A BlueHDi Exclusive Black Top.



Direct Owner

YONG LEE SENG MOTOR PTE LTD

Browse by Category

5 vehicles

Post an Ad

audi rs3

Ways of Selling

Price

Depreciation

Reg Date

Eng Cap Any

Mileage

Sort by Date Posted

Veh Type

Any

Available

Search Selection

audi rs3

Advertiser Login

Model

Anv

\$59,840 /yr

Any

31-Oct-2011

Any

2,480 cc

100,000 km

Any

Sports

Available



Audi RS3 Sportback 2.5A TFSI

\$85,800

✓ 20 results/page

Lowest Depre! Pocket Rocket! Excellent Condition For A Short Term Drive Or Even Renewal! Flexible Loan, 100% Loans And Trade Ins Available! Call Now To Arrange For A Viewing!

Car Empire Automobiles Pte Ltd

Posted: 08-Nov-2020 Tags: 2011 Audi RS3, Audi RS3, Audi, RS3



Audi RS3 Sportback 2.5A TFSI \$128,000 Quattro (New 10-yr COE)

\$12,790 /yr

31-Oct-2011

2.480 cc

136,394 km

Available

Price With Renew COE.

Posted: 07-Oct-2020 Tags: 2011 Audi RS3, Audi RS3, Audi, RS3



Audi RS3 Sportback 2.5A TFSI Quattro

\$83,888

\$33,490 /yr

17-Jul-2012

2,480 cc

Sports

Available

DIRECT OWNER

Stage 2 Revo, TVS TCU, Revo Intake, Wagner Intercooler, Enkei Wheels. Always Parked Under Shelter.

Posted: 06-Nov-2020 Tags: 2012 Audi RS3, Audi RS3, Audi, RS3



Audi RS3 Sportback 2.5A TFSI

\$95,000

\$22,630 /vr

28-Jun-2013

2,480 cc

Sports

Available

Ouattro Rare Audi RS3! Powerful & Responsive 2.5L Turbocharged.Well Maintained, Regularly Serviced And Accident Free. Agent Unit. Feel The Immense Power And Awd Stability Of An Audi Rs At Low Depreciation. Flexible Loan And Trade In Available. Consignment Unit, Kindly C...

Eurospeed Auto

Read this article

Posted: 12-Oct-2020 Tags: 2013 Audi RS3, Audi RS3, Audi, RS3



The Audi RS3 LMS achieves four victories

Audi Sport customer racing celebrates the RS3 LMS entry-level touring car's four victories and nine podiums in Canada and Europe.



Audi RS3 Sportback 2.5A TFSI **Ouattro**

\$228,888

Price

\$23,900 /yr

15-Oct-2018

2,480 cc

20,147 km

Sports

Available

1 Owner, Low Mileage, Accident Free Agent Unit. Fully Serviced & Maintained And Still Under Premium Automobiles Warranty Till Oct

2021. Under Ultilized & Superbly Well Maintained In Immaculate Showroom Condition. Feel The Immense Power And AWD Stability Of A...

Depreciation

CONSIGNMENT

MV Auto

Posted: 10-Nov-2020 Tags: 2018 Audi RS3, Audi RS3, Audi, RS3

Save this search criteria, to get email alerts whenever a match is found.

Model

Reg Date

Eng Cap

Mileage

Veh Type

20 v results/page

For old advertisements, view Expired ads

lew Cars | Used Cars | Rental Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources https://www.sgcarmart.com/used_cars/listing.php?ORD=RGD_ASC&MOD=audi rs3&RPG=20&VEH=0&RGD=&AVL=2



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS

 WORKSHOP
 :
 UBI ROAD 1

 CONTACT NO
 :
 6366 2323

 FAX NO
 :
 6841 1183

REFERENCE : PA/OD/0868/2020/NS

DATE : 13-Nov-20 **WIP** : 57580

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY #07-16 AIG BUILDING SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : DR PHNG HWEE LENG MERVIN

ADDRESS : 4 HOLLAND HEIGHTS

SINGAPORE 249504

TELEPHONE : HP +65 98625072

TYPE OF CLAIM : OWN DAMAGE CLAIM

POLICY NO : 2100385096-06

VEHICLE NO : SKG 3998]

MODEL CODE : AUDI RS 3 SB 2.5 TFSI QU

 MODEL YEAR
 :
 29/8/2012

 ENGINE NO
 :
 CEP 010983

CHASSIS NO : WAUZZZ8P5D1900009

 MILEAGE
 : 49936KM

 DATE IN
 : 12-Nov-20

ESTIMATED BY : JOHNNY BOO / ALLAN WU

ACCIDENT DATE : 3-Nov-20

PLACE OF ACCIDENT : ALONG QUEENSWAY EXIT TO JALAN

BUKIT MERAH





EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKG 3998]

S/N	NATURE OF JOBS		STIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O- LINER.	S/N	\$ 800.00	? *
2	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N	\$ 360.00	V
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N	\$ 1,200.00	Ĵ⊀
4	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY.	S/N	\$ 1,800.00	7/*
	SUB TOTAL LABOUR CHARGES	:	\$ 4,160.00	· :





EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKG 3998]

S/N	NATURE OF JOBS		STIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
3/14	NATORE OF JOBS		CHARGES	
5	TO REMOVE AND REINSTALL CENTRE CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL. INSPECT FOR DAMAGES.	S/N	\$ 3,200.00	
6	TO REMOVE AND REINSTALL RHS FRONT SEAT ASSY, ABCD PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N	\$ 1,800.00	
7	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N	\$ 280.00	
8	TO PLACE VEHICLE ON CAR O-LINER.	S/N	\$ 2,400.00	? X
	SUB TOTAL LABOUR CHARGES	:	\$ 7,680.00	=



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKG 3998]

S/N	NATURE OF JOBS		STIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
9 X 10	TO DISMANTLE FRONT BUMPER, BONNET, BOTH FRONT FENDERS, BOTH HEADLIGHTS, RHS FRONT DOOR AND RHS SILL PANEL TRIM. CUT OUT AND REWELD RHS LOWER A-PILLAR AND RHS SILL PANEL. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, RHS LOWER A-PILLAR, RHS SILL PANEL, RHS SILL PANEL TRIM, DOOR ENTRANCE, RHS FRONT DOOR, RHS WING MIRROR COVER AND DOOR COVER. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT.		\$ 9,800,00	7x550=3850 Roor Cour: 150 Mirror: 150
11	TO RENEW BOTH FRONT RIMS. TO CARRY OUT PRE AND POST REPAIR WHEEL ALIGNMENT CHECK.	'N	\$ 560,00	320.
12	TO CARRY OUT PRE AND POST REPAIR DIAGNOSTIC CHECK.	/N	\$ 384.00	//
	SUB TOTAL LABOUR CHARGES		\$ 30,484.00	





EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKG 3998]

S/N PARTS DESCRIPTION	QTY	 DAMAGED PARTS S/NETT	& PRICES REMARKS
1 FRONT BUMPER Distorted		\$ 5,789.00	4631.20
2 FRONT BUMPER FIXING PARTS At ~		\$ 258.00	+
3 FRONT BUMPER CARRIER Mem		\$ 1,145.00	+
4 FRONT BUMPER SHOCK ABSORBER - LH	M	\$ 342.00	<i>t</i> ,
5 FRONT BUMPER GUIDE SECTION - LH/RH	mg	\$ 624,00	312 249.20
6 RADIATOR GRILLE could		\$ 4,201.00	√ 3360.80
7 RADIATOR GRILLE CLOSING ELEMENT Not	mer	\$ 647.00	? XI
8 RS3 INSCRIPTION HU	D	\$ 122.00	19760
9 FRONT BUMPER AIR GUIDE GRILLE - LH/RH	n 2	\$ 832.00	+
10 FRONT BUMPER END CAP THE MIN		\$ 268.00	?X
11 FRONT BUMPER TRIM STRIPS - LH/RH	e me	\$ 850.00	2 ×
12 FRONT BUMPER SPOILER - LOWER CENTRE	lph	\$ 1,411.00	+
13 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	The rec	\$ 397.00	,X
14 FRONT BUMPER FOAM FILLER PIECE	_	\$ 268.00	+
15 SPRING SHACKLE		\$ 66.00	+
16 SIGNAL HORN - LOW/HIGH TONE Note	2	\$ 446.00	*
17 FRONT FENDER - LH/RH Drolt	2	\$ 12,602.00	10,081.60
18 FRONT FENDER BRACE - LH FRONT		\$ 53.00	7 42-24
19 FRONT FENDER BRACKET - LH/RH LOWER 🏾 🎾	76 2	\$ 162.00	128.80
20 FRONT FENDER CLOSING ELEMENT - LH/RH	W 2	\$ 184.00	7 147.04
SUB TOTAL SPARE PARTS	mle -	\$ 30,667.00	:





EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKG 3998]

S/N PARTS DESCRIPTION	ОТУ	DAMAGED PARTS & PRICES S/NETT REMARKS
Om to	in	
21 WHEEL HOUSING LINER - LH/RH INNER	2 \$	586,00° 293. HG8
22 WHEEL HOUSING LINER - LH/RH OUTER	2 🗸 \$	586,00° 293. 468
23 WHEEL SPOILER - LH/RH LH ton	2 \$	134,00 67. 53.44
24 WHEEL HOUSING SOUND ABSORBER - LH/RH	the mers	212.00
25 BONNET	\$	2,373.00 *
26 BONNET LID HINGE - LH/RH	2 \$	114.00
27 BONNET CATCH HOOK	\$	92.00 🗶
28 BONNET LID LOCK	\$	212.00 K
29 BONNET LOCK COVER - UPPER FRONT	\$	51.00 T
30 HEADLIGHT-LH/RH LH Could	2 \$	4,556.00 22 78 1822.40
31 GAS DISCHARGE LAMP Z	\$	408.00 +
32 GAS DISCHARGE LAMP CONTROL UNIT wen	\$	1,084.00 *
33 CORNERING LIGHT POWER MODULE	\$	1,043.00 *
34 HEADLIGHT HOSE - LH Men	\$	12.00 F
35 FLAT CONTACT HOUSING Her cruled	\$	30.00 × 23.60
36 LIFT CYLINDER - LH Couled.	\$	201.00 + 160.80
37 LIFT CYLINDER HOSE Noch	5 \$	184.00 £
38 WASH WATER RESERVOIR	\$	170.00
39 LOCK CARRIER FUR MEC.	\$	2,289.00
40 AIRCON CONDENSER Not M	\$	1,079.00 🗶
SUB TOTAL SPARE PARTS	: \$	15,416.00





EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKG 3998]

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT REMARKS
41 AIRCON STICKER XLL	NEC	\$ 18.00 / 13.84
42 ADDITIONAL RADIATOR Men		\$ 1,874.00
43 ADDITIONAL RADIATOR BRACKET - LH/RH /	2	\$ 426.00
44 READY MIX COOLANT Not New		\$ 91.00 🔞 🔨
45 RADIATOR AIR GUIDE - LH We New		\$ 39.00 ⁷ ×
46 RADIATOR AIR GUIDE - LH OUTER W	L.	\$ 78.00 7 ×
47 FRONT DOOR - RH Dishild		\$ 2,176.00 1740.80
48 FRONT DOOR HINGE - RH LOWER Bent.		\$ 237.00 7 189.60
49 FRONT DOOR HINGE - RH UPPER	L	\$ 71.00 ? 📉
50 DOOR HINGE RETAINING PLATE Not No.		\$ 13.00 7 🗡
51 FRONT DOOR SIDE REINFORCEMENT Not N	u	\$ 157.00 ? X
52 FRONT DOOR INNER SEAL NEC		\$ 250.00
53 TYRE PRESSURE DATA PLATE		\$ 20.00 15.36
54 EXTERIOR MIRROR MOUNTING - RH	me	\$ 1,013.00
55 MIRROR CAP - RH Lt		\$ 1,282.00 / 1035.60
56 MIRROR GLASS - RH HEL		\$ 1,644.00 +
57 TURN SIGNAL INDICATOR HUM		\$ 99.00 +
58 FRONT DOOR COVER - RH Drolld	,	\$ 326.00 260.80
59 FRONT DOOR PROTECTIVE STRIP - RH	_d	\$ 201.00
60 SIDE MEMBER TRIM - RH Districted		\$ 1,029.00
SUB TOTAL SPARE PARTS	:	\$ 11,044.00





EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKG 3998]

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT REMARKS
61 SIDE MEMBER TRIM CAP-RH Missing .		\$ 164.00
62 A-PILLAR-RH Dishite		\$ 1,120.00
63 SILL TRIM STRIP - RHOUTER THE NEW		\$ 679.00
64 SILL TRIM STRIP - RH INNER The MEC		\$ 187.00 7 🗶
65 DATA TAG Not Mer		\$ 457.00 ⁷ ×
66 NOISE INSULATION 7		\$ 746.00 ? ×
67 UNDERBODY TRIM NEC		\$ 245.00
68 FRONT ALUMINIUM RIM - LH/RH	2	\$ 2,728.00 >182.40
69 TRACK CONTROL ARM - LH Z		\$ 371.00
70 WHEEL BEARING HOUSING - LH & NEC		\$ 666.00
71 WHEEL BEARING 2005		\$ 949.00 ? 759.00
72 GUIDE JOINT - LH Bent		\$ 136.00 ? 108:40
73 TIE ROD END - LH		\$ 122.00 ? 🔀
74 STONE CHIP Not Nec	S/N	\$ 180.00 ? 🗶
75 CAVITY WAX Not wee	S/N	\$ 140.00 ² ×
76 ACRYLIC SEALANT Not wee	S/N	\$ 180.00 ? 🔨
77 FRONT NO PLATE HE	S/N	\$ 60.00
78 SUNDRIES Nec.		\$ 400.00 HH5-12
TOTAL SPARE PARTS	:	\$ 66,657.00
TOTAL LABOUR CHARGES	:	\$ 30,484.00
GRAND TOTAL	:	\$ 97,141.00

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

Me Antlansed, 12 Days

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE

AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF

REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO

MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY, PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO BODY REPAIR MANAGER ALLAN WU CLAIMS CONSULTANT

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Veron

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0868/2020/NS

3-Dec-20

CHANG

1 of 1

SKG 3998 J

AUDI RS3 SB 2.5 TFSI QU

Quantity	Description	Unit Price	Amount
Parts 1	HEADLIGHT MOUNTING - LH Cruld	\$ 117.00 L	/93.60
	GRAND TOTAL	\$ 117.00	

For Premium Automobiles Pte Ltd

Adrian G 03/12/20 Resuzed

Authorised Signature