

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Sheraton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Quotation
 DATE : 02.12.2020
 VEH NO : SKE8118K
 MODEL : Mercedes E250
 D O A : 13.11.2020
 YR REF : SJU447R

Jasper

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SKE8118K (MERCEDES E250)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Number Plate Garnish <i>new</i>	1	88.00 <i>x.</i>
2	Front Bumper <i>Deformed.</i>	1	1,510.00 <i>✓</i>
3	Front Bumper Side Holder <i>RH new</i>	2	130.00 <i>65.</i>
4	Front Bumper Sensor <i>1 piece damaged</i>	3	795.00 <i>265</i>
5	Front Bumper Washer Pump - RH <i>new</i>	1	152.00 <i>✓</i>
6	Front Bumper Washer Pump Cover - RH <i>Missing</i>	1	25.00 <i>✓</i>
7	Front Bumper Sponge <i>3 new</i>	1	123.00 <i>✓</i>
8	Front Bumper Reinforcement	1	608.00 <i>x.</i>
9	Front Bumper Side Grille Chrome - Rh <i>wt 4050</i>	1	95.00 <i>✓</i>
10	Front Grille <i>new</i>	1	1,183.00 <i>x</i>
11	Head Lamp - RH <i>cracked</i>	1	2,090.00 <i>✓</i>
12	Bonnet <i>Ryis</i>	1	2,510.00 <i>x</i>
13	Bonnet Logo <i>new</i>	1	90.00 <i>x.</i>

Less 10%

9,399.00
 (939.90)
 \$ 8,459.10

S/NETT ITEMS

1	Front Number Plate <i>3 new</i>	1	\$ 30.00 <i>x</i>
2	Front Number Plate Holder	1	\$ 30.00 <i>x</i>
3	Front Bumper Clips <i>new</i>	1 set	\$ 50.00 <i>30</i>
4	Front Grille Clips <i>new</i>	1 set	\$ 30.00 <i>x.</i>

\$ 140.00

Total Parts

\$ 8,599.10

RE : ESTIMATE FOR ACCIDENT REPAIR SKE8118K (MERCEDES E250)

LABOUR CHARGE

1	To knocking & pull out front RH portion & renew above parts	\$	600.00	350
2	To putty & spray up paint works	\$	600.00	500
3	To check wiring	\$	50.00	30
4	To remove front bumper sensor	\$	120.00	60
5	To spray tuff coat	\$	150.00	40
Total Labour		\$	1,520.00	
Grand Total		\$	10,119.10	

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 4655

4/s: 3.7K.
04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: