

# 輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721  
Tel: 64515752 (2 Lines) . Fax: 64514658  
GST & Reg No. 201629438M

*AKG*  
*LKK*  
*Kenneth*  
*17/11/20*

12/11/2020

Owner: HYMS CAR LEASING PTE LTD

*Not withain*  
*11 Rep @ 2050/hr*  
*Penalty After Paint*  
*3 days*

**ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID 1.8S A - SMG1384U**

1pc	rear tailgate "PRIUS" emblem	<i>NR</i>	\$ 61.75	—
1pc	rear tailgate "HYBRID" emblem	<i>NR</i>	\$ 53.75	—
1pc	rear tailgate "TOYOTA" logo	<i>NR</i>	\$ 61.10	—
1pc	rear tailgate outer garnish <i>741.35</i>	<i>MYGMA</i>	\$ 741.35	✓
1pc	rear tailgate inner rubber	<i>SR</i>	\$ 281.50	X
1pc	rear bumper <i>512.60</i>	<i>BR</i>	\$ 928.35	✓
2pcs	rear bumper side retainer @\$141.40	<i>SR</i>	\$ 282.80	X
1pc	rear bumper diffuser	<i>CM</i>	\$ 379.00	✓
1pc	rear bumper reinforcement <i>350.50</i>	<i>AR</i>	\$ 458.00	✓
1pc	rear bumper towing cover	<i>SR</i>	\$ 61.00	X
1pc	rear end panel	<i>R</i>	\$ 970.25	X
1pc	rear end panel inner garnish	<i>SR</i>	\$ 381.90	X
			\$ 4,660.75	
less 25%			\$ 1,165.19	
			\$ 3,495.56	

1set rear parking sensor *Shan* s.nett \$ 280.00 *2008*

tuffkote  
wiring  
spray painting  
labour charges  
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

<i>NR</i>	\$ 100.00	X
	\$ 80.00	<i>15hr</i>
	\$ 1,000.00	<i>440L</i>
	\$ 1,000.00	<i>300L</i>
		\$ 5,955.56

