



Ngai Hong Auto Services

160 Sin Ming Drive #06-08 Sin Ming AutoCity Singapore 575722

Tel : 64531712 Fax : 62666402 HP : 96779434

Email : yewhaw@ngaihongsp.com

QUOTATION

UEN No: 53368670M

To : Anna Moel Yono

QTN No : Q96/20

Date : 18/11/2020

Attn :

Dear Sir / Madam,

QUOTATION

Vehicle No : SMS 6755 L

Make/Model : Mitsubishi Outlander

S/No	Description	Qty	UI	Unit Price	Amount
1	Front RH Fender <i>Repair x</i>	1	Pcs	\$702.00	\$702.00 X
2	Front RH Fender Arch <i>✓ Ser.</i>	1	Pcs	\$179.00	\$179.00 ✓
3	Front RH Headlamp Assembly <i>✓ Ser.</i>	1	Pcs	\$1,916.00	\$1,916.00 1852
4	Front RH Headlamp Chrome Moulding <i>✓ Ser.</i>	1	Pcs	\$70.00	\$70.00 ✓
5	Front RH Headlamp Washer Cover <i>✓ Cut.</i>	1	Pcs	\$65.00	\$65.00 ✓
6	Front RH Headlamp Washer Nozzle <i>✓ DM.</i>	1	Pcs	\$263.00	\$263.00 ✓
7	Front Bumper <i>✓ Re</i>	1	Pcs	\$1,084.00	\$1,084.00 ✓
8	Front Bumper Reinforcement <i>X MV.</i>	1	Pcs	\$565.00	\$565.00 X
9	Front Bumper RH Retainer <i>✓ BR.</i>	1	Pcs	\$52.00	\$52.00 24
10	Front Bumper RH Side Garnish <i>✓ Ser.</i>	1	Pcs	\$109.00	\$109.00 ✓
11	Front Bumper RH Top Chrome Moulding <i>✓ Cut.</i>	1	Pcs	\$198.00	\$198.00 106
12	Front RH Fog Lamp Assembly <i>✓ BR.</i>	1	Pcs	\$252.00	\$252.00 223
13	Front RH Fog Lamp Cover <i>✓ Cut</i>	1	Pcs	\$134.00	\$134.00 20
14	Front RH Fog Lamp Cover Chrome <i>✓ BR</i>	1	Pcs	\$131.00	\$131.00 50
15	Front RH Sport Rim <i>Repair - x</i>	1	Pcs	\$715.00	\$715.00 X

Grand-Total

We hope you will find our quote satisfactory and look forward to your favourable reply. Thank you.

Your Sincerely

NGAI HONG AUTO SERVICES

Teo Yew Haw

Ngai Hong Auto Services

160 Sin Ming Drive #06-08 Sin Ming AutoCity Singapore 575722
Tel : 64531712 Fax : 62666402 HP : 96779434
Email : yewhaw@ngaihongsp.com

QUOTATION

UEN No: 53368670M

To : Anna Moel Yono

QTN No : Q96/20
Date : 18/11/2020

Attn :

Dear Sir / Madam,

QUOTATION

Vehicle No : SMS 6755 L
Make/Model : Mitsubishi Outlander

S/No	Description	Qty	UI	Unit Price	Amount
	Labour charges :				
16	To dismantle above damaged parts, repair including cut and weld; re-align body structure and damaged consistent to the accident.			250.00	\$850.00
17	To spray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.			800	\$650.00
18	To check wiring, lighting and resetting headlamp focusing			30	\$120.00
19	To remove and renew front RH sport rim.			30	\$70.00

4 Days.

Lump sum repair

After repair photos.

Guo Ri ang - 888 asfz

810

4450.5

20% = 890.1

Grand Total

\$8,125.00

We hope you will find our quote satisfactory and look forward to your favourable reply. Thank you.

Your Sincerely

NGAI HONG AUTO SERVICES

Teo Yew Haw

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplemental survey is resurveyed and is subject to the Insurance Company

Acknowledge

Signature

Date