

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

VEHICLE NO : GBK7621E

MAKE & MODEL : NISSAN/NV350 PANEL VAN 2.5MT 5DR

CHASSIS NO : JN1MC2E26Z0032132

DATE : 19 NOV 2020

CLAIM TYPE : TP CLAIM

D.O.A : 14 NOV 2020

TO : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	LIST PRICE	TOTAL PRICE
1	1	FRONT BUMPER	BR	\$ 571.90	\$ 571.90
2	1	FRONT BUMPER SIDE RETAINER	BR	\$ 147.00	\$ 147.00
3	1	FRONT FOG LAMP GARNISH LH	X NM	\$ 104.70	\$ 104.70
4	1	HEADLAMP ASSY LH	CNT	\$ 672.00	\$ 481 / 672.00
5	1	FRONT STEP PANEL GARNISH LH	X NM	\$ 235.00	\$ 235.00
6	1	FRONT WHEEL HUB CAP LH	X NM	\$ 151.20	\$ 151.20
7	1	SIDE MIRROR LH	X NM	\$ 553.90	\$ 553.90
				\$ 2,435.70	\$ 2,435.70

1,199.9
- 10%
1079.91

TOTAL PRICE	\$ 2,435.70
DISCOUNT: 10%	\$ 243.57
SUB TOTAL PRICE	\$ 2,192.13

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	FRONT BUMPER CLIPS SET	MC	\$ 50.00	\$ 30 / 50.00
2	1	COMPANY REGISTRATION STICKER	ARC	\$ 30.00	\$ 30.00

TOTAL S/NETT \$ 80.00 \$ 80.00

Labour Charges

1	To panel beat & straighten damaged panels. To remove & replace parts.	\$ 700.00	200
2	To apply anti rust coat and Tuff Kote affected areas	\$ 50.00	30
3	To check and rectify lighting & wiring harness	\$ 50.00	30
4	To Spray painting Front Bumper & front left door & affected parts	\$ 700.00	400
5	To do artwork company sticker.	\$ 300.00	150

TOTAL LABOUR

Total Cost of Repairs

(Total parts + Total S/Nett + Total Labour Cost)

\$ 1,800.00
\$ 4,072.13

Stere (LKK)

WAL AL

9/12/20, 9.15am

3 days

P/P

Ry BOL SM

= 1949.91

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: