



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC20009444/Gtf3e2-1

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 03-12-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 9923M	Veh. Inspected	YN 8114H
Policy No.		Coverage (\$)	0.00
Claim No.	20/20/20/VC05/023622	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	17/11/2020

2. Vehicle Particulars & Condition

Make & Model	ISUZU NPR85UH5A 3.0	c.c	2999
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JAANPR85HF7100196	Colour	BLUE
Odometer	311702	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/85 R16	WEST LAKE	6 mm
L/H Front Tyre	195/85 R16	WEST LAKE	6 mm
R/H Rear Tyre	205/85 R16	HANKOOK	6 mm
L/H Rear Tyre	205/85 R16	HANKOOK	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/09/2020	Inspection Date	21/09/2020
Survey held at	MJE MOTOR BLK 7 SIN MING IND EST SEC C #01-96 SINGAPORE 575642		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	1 Working Days
-------------------------------------	----------------