

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : **SGF 7612 Z**
Make : Toyota
Model : Wish
Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	2006 TOTAL S\$
1	Tailgate	1	\$ 1,103.20	\$ 1,103.20
2	Tailgate logo	1	\$ 106.30	\$ 76.80
3	Tailgate inner trim board	1	\$ 585.20	\$ 485.10
4	Tailgate outer chrome garnish	1	\$ 262.40	\$ 262.40
5	Tailgate weatherstrip	1	\$ 214.60	\$ 165.00
6	Tailgate stopper	2	\$ 65.80	\$ 131.60
7	Tailgate inner lock	1	\$ 401.50	\$ 392.00
8	Tailgate inner lock sticker	1	\$ 62.30	\$ 62.30
9	Tailgate inner handle	1	\$ 66.80	\$ 66.80
10	Tailgate wiper motor	1	\$ 468.50	\$ 468.50
11	Tailgate windscreen moulding	1	\$ 287.00	\$ 165.00
12	Tailgate number plate lamp	2	\$ 48.00	\$ 96.00
13	Tail gate hydraulic damper	2	\$ 202.00	\$ 404.00
14	Rear bumper	1	\$ 827.60	\$ 566.10
15	Rear bumper side retainer	2	\$ 60.00	\$ 120.00
16	Rear bumper reflector	2	\$ 75.00	\$ 150.00
17	Rear bumper support bracket	2	\$ 137.40	\$ 274.80
18	Rear end panel	1	\$ 748.60	\$ 480.00
19	Rear end panel top garnish	1	\$ 321.20	\$ 289.00
20	Rear floor panel	1	\$ 1,052.30	\$ 1,052.30
21	Rear floor panel top board	1	\$ 580.00	\$ 580.00
22	Rear floor panel board top side board	2	\$ 318.20	\$ 636.40
23	Rear floor panel top board rear garnish	1	\$ 398.00	\$ 398.00
24	Rear fender	2	\$ 913.60	\$ 1,827.20
25	Rear fender inner trim board	2	\$ 615.00	\$ 1,230.00
26	Rear fender side glass moulding	2	\$ 141.50	\$ 283.00
27	Spare tyre carrier	1	\$ 245.00	\$ 245.00
28	Spare tyre carrier bolt	1	\$ 45.00	\$ 45.00
29	Taillamp	2	\$ 380.40	\$ 760.80
30	Exhaust pipe	1	\$ 910.00	\$ 910.00
31	Exhaust pipe mounting	2	\$ 68.00	\$ 136.00

DD✓
NEC✓
BR✓
BR✓
TN✓
NNX
JMV✓
NDX
BR✓
NDX
NEC✓
NDX
JMV✓
BR✓
NEC✓
BR✓
NSX
DD✓
BR✓
NDX
NDX
NDX
NDX
NDX
CUTXR
BR✓
NNX
NDX
BR✓
DDXR
NDX

6716.20
@ 20% 1679.65
5037.15

Parts Sub Total : \$ 15,738.10
Discount : \$ 3,934.53
PARTS TOTAL : \$ 11,803.58

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Tailgate sealant	1	\$ 100.00	\$ 100.00
3	Tailgate inner trim board clips	1	\$ 50.00	\$ 50.00
4	Tailgate outer chrome moulding clips	1	\$ 50.00	\$ 50.00
5	Tailgate windscreen sealant	1	\$ 120.00	\$ 120.00
6	Tailgate windscreen inner seal	1	\$ 60.00	\$ 60.00
7	Tailgate windscreen primer & cleaner	1	\$ 80.00	\$ 80.00
8	Rear bumper clips	1	\$ 50.00	\$ 50.00
9	Rear end panel sealant	1	\$ 100.00	\$ 100.00
10	Rear end panel top garnish clips	1	\$ 50.00	\$ 50.00
11	Rear floor panel sealant	1	\$ 100.00	\$ 100.00
12	Rear floor panel top board rear garnish clips	1	\$ 50.00	\$ 50.00
13	Rear fender sealant	1	\$ 100.00	\$ 100.00
14	Rear fender inner trim board clips	2	\$ 50.00	\$ 100.00
15	Rear fender side glass sealant	1	\$ 100.00	\$ 100.00
16	Rear fender side glass inner seal	1	\$ 80.00	\$ 80.00
17	Rear fender side glass primer & cleaner	1	\$ 60.00	\$ 60.00
18	Taillamp clips	2	\$ 50.00	\$ 100.00
19	Taillamp seal	2	\$ 60.00	\$ 120.00
20	Rear number plate w/casing	1	\$ 80.00	\$ 80.00
21	Reverse sensor	2	\$ 250.00	\$ 500.00
SPECIAL NETT TOTAL :				\$ 6,770.00 2,130.00

Nos.	LABOUR	S\$
1	R&R tailgate componnet	\$ 80.00 150.00
2	R&R tailgate windscreen	\$ 120.00 250.00
3	R&R reverse sensor	\$ 60.00 100.00
4	R&R rear side glass	\$ 150.00
5	R&R fuel tank pipe	\$ 150.00
6	R&R exhaust pipe	\$ 60.00 150.00
7	Check wiring	\$ 50.00 100.00
8	Upholstery	\$ 300.00
9	Panel beat	\$ 1,000.00 1,800.00
10	Rust proofing	\$ 60.00 200.00
11	Spray painting	\$ 1,000.00 1,800.00
LABOUR TOTAL :		\$ 5,150.00

Tellim lui

Tellim lui

Survey 17/11/2020

Resurvey 18/11/2020

1400hrs

LABOUR TOTAL : 8137.15

PARTS TOTAL : \$ 11,803.58

SPECIAL NETT TOTAL : \$ 2,130.00

LABOUR TOTAL : \$ 5,150.00

GRAND TOTAL : \$ 19,083.58

Lump sum repair
Repair days 8

PARTS 5037.15

S/N 670.00

LABOUR 2430.00

8137.15

1627.43

6509.72

@ 2090

4/5 6500/2

Tellim lui
25/11/2020

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Prepared by Eric (8269-9999) Page 2 of 2