

ASS. REC. BY:

REF:

MSG/ 20012674/KC Kcd3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STS 3133L

Yr Regn:

02 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mc S350L

c.c

3498

Colour

M. Black

A/C: Insured / Std / NI / NA

Sp. Reading

138314

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD 2211562 A106096

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/40R20

R:

275/35R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

16/11/20

D.O.I.

18/11/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rpt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/11/2020 @ 8:00 AM Good (Red & 73 mm. 10, 77%)

Date/Time, File Pass to?

☐

Prell. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + R.S. SI

F.M.S

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

MER-TP

Lump Sum / L.B.I. (\$

9000

Not Authorized
11 Sep 89000h
Returning After Paint

TO :
ATT : MOTOR CLAIM DEPT.

T/P VEH. NO. : SLF1913K

ESTIMATE REPORT 1st QUOTATION

JOB NO. : _____

OWNER'S PARTICULAR

NAME : CARZBOND

CONTACT :

ADDRESS :

LICENSE NO. : SJS3133L

CHASSIS NO : WDD2211562A106696

MAKE / MODEL : MERCEDES SCLASS

ENGINE NO :

OWNER'S INSURER :

JOB-CODE : TP S/A :

ACCIDENT DATE : 16-Nov-20

CLAIM DETAIL

MATERIALS

		QTY	QUO-PRICE	DISC. %	DISC- PRICE	SUK DIED	REV. PRICE
1	HEADLAMP RH	1.00	3817.00	10.00	3435.30	Y	X
2	HEADLAMP LH 3659.12	1.00	3817.00	10.00	3435.30	Y	✓
3	HEADLAMP BRACKET LH	1.00	189.00	10.00	170.10	Y	✓
4	FRONT BUMPER 2240 (Amgr) Bu	1.00	3956.00	10.00	3560.40	Y	✓
5	FRONT BUMPER INNER PLASTIC 184	1.00	295.00	10.00	265.50	Y	✓
6	FRONT BUMPER REINFORCEMENT 685	1.00	1730.00	10.00	1557.00	Y	✓
7	FRONT BUMPER BRACKET LH	1.00	170.00	10.00	153.00	Y	✓
8	FRONT BUMPER BRACKET RH	1.00	170.00	10.00	153.00	Y	X
9	FRONT BUMPER RETAINER RH	1.00	80.00	10.00	72.00	Y	X
10	FRONT BUMPER RETAINER RH	1.00	80.00	10.00	72.00	Y	✓
11	FRONT NOZZLE COVER LH	1.00	87.00	10.00	78.30	Y	✓
12	FRONT BUMPER NOZZLE COVER BRACKET LH 115	1.00	170.00	10.00	153.00	Y	✓
13	FRONT BUMPER NOZZLE COVER BRACKET RH	1.00	170.00	10.00	153.00	Y	X
14	FRONT BUMPER LED LAMP LH 485	1.00	526.00	10.00	473.40	Y	✓
15	FRONT BUMPER LED LAMP RH	1.00	526.00	10.00	473.40	Y	X
16	FRONT BUMPER LED COVER RH	1.00	80.00	10.00	72.00	Y	X
17	FRONT BUMPER LED COVER LH	1.00	80.00	10.00	72.00	Y	✓
18	FRONT AIR DUCT LH	1.00	126.00	10.00	113.40	Y	X
19	FRONT BUMPER CHROME CENTRE 6m16	1.00	155.00	10.00	139.50	Y	X
20	FRONT BUMPER SPONGE CENTRE 122	1.00	149.00	10.00	134.10	Y	✓
21	FRONT BUMPER SPONGE SIDE LH	1.00	92.00	10.00	82.80	Y	X
22	FRONT BUMPER SENSOR 6 PCS \$356X6 @ 228.40	2.00	2136.00	10.00	1922.40	Y	4 456.80

23	FRONT BUMPER SENSOR HOLDER 6PCS	<i>me</i> 6.00	<i>nn</i> 720.00	10.00	648.00	Y	<i>2x</i>
24	FRONT BUMPER SENSOR WIRE HARNESS <i>301.</i>	<i>cm</i> 1.00		453.00	10.00	407.70	Y <i>2</i>
25	FRONT BUMPER LOWERCENTRE GRILLE	1.00	<i>sn</i> 222.00	10.00	199.80	Y	<i>x</i>
26	FRONT BUMPER LOWER COVER	1.00	<i>cm</i> 142.00	10.00	127.80	Y	<i>✓</i>
27	FRONT BUMPER LOWER BRACKET LH	<i>R</i> 1.00		85.00	10.00	76.50	Y <i>2</i>
28	FRONT BUMPER NO. PLATE GARNISH	1.00	<i>sn</i> 110.00	10.00	99.00	Y	<i>x</i>
29	RADIATOR GRILLE <i>833</i>	<i>E</i> 1.00	<i>nd</i> 996.00	10.00	896.40	Y	<i>✓</i>
30	AIR MATIC RESERVOIR TANK <i>381.60</i>	<i>nd</i> 1.00		430.00	10.00	387.00	Y <i>2</i>
31	AIR MATIC RESERVOIR TANK PIPE 1 SET	<i>cm</i> 1.00		89.00	10.00	80.10	Y <i>2</i>
32	RADIATOR ASSY	1.00	<i>sn</i> 2150.00	10.00	1935.00	Y	<i>x</i>
33	RADIATOR SIDER GARNISH LH <i>185</i>	<i>cm</i> 1.00		240.00	10.00	216.00	Y <i>2</i>
34	RADIATOR LOWER MEMBER	1.00	<i>R</i> 510.00	10.00	459.00	Y	<i>x</i>
35	RADIATOR LOWER STOPPER RH	1.00	<i>R</i> 35.00	10.00	31.50	Y	<i>x</i>
36	RADIATOR LOWER STOPPER LH	<i>sn</i> 1.00		35.00	10.00	31.50	Y <i>2</i>
37	AIR CON CONDENSER	1.00	<i>sn</i> 2000.00	10.00	1800.00	Y	<i>x</i>
38	AIR CON CONDENSER GARNISH HOLDER	1.00	<i>sn</i> 444.00	10.00	399.60	Y	<i>x</i>
39	HEADLAMP NOZZLE LH	1.00	<i>mi</i> 180.00	10.00	162.00	Y	<i>✓</i>
40	FRONT FENDER LH	1.00	<i>R</i> 1475.00	10.00	1327.50	Y	<i>x x</i>
41	FRONT FENDER CHROME MOUNTING	1.00	<i>me</i> 97.00	10.00	87.30	Y	<i>✓</i>
42	FRONT FENDER INNER SHIELD LH no.1	<i>cm</i> 1.00		122.00	10.00	109.80	Y <i>2</i>
43	FRONT FENDER INNER SHIELD LH no.2	<i>sn</i> 1.00		102.00	10.00	91.80	Y <i>2</i>
44	ENGINE MOUNTING LH	<i>R</i> 1.00		346.00	10.00	311.40	Y <i>x</i>
45	ENGINE MOUNTING RH	<i>sn</i> 1.00		346.00	10.00	311.40	Y <i>x</i>
46	FRON LOWER ARM LH	<i>sn</i> 1.00		865.00	10.00	778.50	Y <i>x</i>
47	FRONT CONTROL ARM LH	<i>sn</i> 1.00		985.00	10.00	886.50	Y <i>x</i>
48	HEADLAMP LOWER BEAM LH	<i>sn</i> 1.00		189.00	10.00	170.10	Y <i>x</i>

TOTAL (PARTS) :

31969.00

28772.10

SPECIAL NETT ITEM

1	FRONT BUMPER CLIPS 1SET	1.00	80.00	0.00	<i>me</i> 80.00	Y	<i>✓</i> <i>50sn</i>
2	RADIATOR COOLANT	1.00	80.00	0.00	<i>nn</i> 80.00	Y	<i>x</i>
3	FRONT FENDER INNER SHIELD CLIPS	1.00	80.00	0.00	<i>me</i> 80.00	Y	<i>✓</i> <i>50sn</i>

4	FRONT BUMPER LOWER COVER CLIPS	1.00	80.00	0.00	<i>Mr</i> 80.00	Y	<u>✓</u>
5	FRONT NUMBER PLATE	1.00	50.00	0.00	<i>Mr</i> 50.00	Y	<u>X</u>

TOTAL (PARTS) : 370.00 370.00

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	1.00	1200.00	0.00	1200.00	Y	<u>500</u>
2	SPRAY PAINTING ON ACCIDENT AREAS	1.00	1000.00	0.00	1000.00	Y	<u>700</u>
3	R&R AIR CON CONDENSOR AND TOP UP GAS	1.00	180.00	0.00	180.00	Y	<u>X</u>
	RAMOVE AND REFIT RADIATOR TO ASSIST REPAIR	1.00	180.00	0.00	180.00	Y	<u>X</u>
4	RESET BUMPER SENSOR AND CALIBRATION	1.00	180.00	0.00	180.00	Y	<u>60</u>
5	CONDUCT FULL WHEEL ALIGNMENT	1.00	120.00	0.00	120.00	Y	<u>X</u>
6	R&R FRONT SUSPENSIONS SYSTEM	1.00	280.00	0.00	280.00	Y	<u>X</u>

TOTAL (LABOUR) : 3140.00 3140.00

TOTAL PARTS & LABOUR 35479.00 32282.10

EXCESS : : S\$

NO. OF DAY : 06

RE-SURVEY : ~~BEFORE~~ / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : S\$

DATE OF SURVEY : 18 / 11 / 20

SURVEY BY : Kenneth

CONTACT NC :

FAX NO :

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	058E
Vehicle Details	
Vehicle No.:	SJS3133L
Vehicle to be Exported:	Yes
Intended Deregistration Date:	16 Nov 2020
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	S350L
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	27296530523459
Chassis No.:	WDD2211562A106696
Maximum Power Output:	200.0 kW (268 bhp)
Open Market Value:	\$99,906.00
Original Registration Date:	06 Feb 2007
First Registration Date:	06 Feb 2007
Transfer Count:	2
Actual ARF Paid:	\$109,897.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	05 Feb 2027
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$52,077.00
COE Rebate Amount:	\$32,401.00
Total Rebate Amount:	\$32,401.00

The information contained herein is correct as at 16 Nov 2020

OK