LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Jenny Lew Date: 20 Nov 2020

Preliminary Advice

Insured Vehicle No : SLV970S

TP Vehicle No : FBQ1533J Accident Date : 07/11/2020 Make : YAMAHA Y125Z Assignment Date : 18/11/2020

Date of Inspection : 18/11/2020 Est. Duration of Repair : 5

Inspection At : Hkl Lim Team Motorsport (HQ)

BLK 1008 #01-24 BUKIT MERAH LANE 3

Singapore 159722

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,553.00
Revised Amount	:S\$	6,283.00
Check Items (Estimated)	:S\$	2,290.00
Total	:S\$	8,573.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :\$\$
Pre-Accident Value :\$\$
COE / PARF Rebate :\$\$
Salvage Value :\$\$
Margin for Repair :\$\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: TP: WP