



HKL LIM
TEAM MOTORSPORT

Blk 1008 #01-24, Bukit Merah Lane 3, Singapore 159722 Tel: 6275 6656, 6275 6566, 62727292 Fax: 6272 9291
Email: support@hklilmotorsport.com.sg Website: www.hklilmotorsport.com.sg

FBQ1533J

- 1 LAMP STAY
- 2 METER ASSY
- 3 FRONT FORK ASSY LH/RH
- 4 FRONT FORK UNDER BRACKET
- 5 STEERING CONE BEARING
- 6 FRONT FORK UPPER CLAM
- 7 BODY FRAME ALIGNMENT
- 8 FRONT FENDER
- 9 FRONT FENDER BRACKET
- 10 FRONT WHEEL RIM
- 11 FRONT WHEEL SHALF
- 12 FRONT WHEEL BEARING 2PCS
- 13 FRONT WHEEL BEARING OIL SEAL
- 14 FRONT BRAKE DISC
- 15 FRONT BRAKE CALIPER
- 16 FRONT SIGNALS LH/RH
- 17 IU UNIT
- 18 IU UNIT BRACKET
- 19 HANDLE BAR
- 20 HANDLE BAR GRIP
- 21 HANDLE BAR BALANCER
- 22 WINDSHIELD
- 23 FRONT NO PLATE
- 24 BRAKE LEVER
- 25 CLUTCH LEVER
- 26 SIDE MIRROR
- 27 HEADLIGHT
- 28 HEAD CAWRING CENTER
- 29 HEAD CAWRING LH
- 30 HEAD CAWRING RH
- 31 FRONT BRAKE PUMP
- 32 FRONT BRAKE HOSE
- 33 REAR FARK REST RH
- 34 FRONT FARK RECFATOR LH/RH
- 35 FUEL TANK INNER PANEL LH/RH
- 36 FUEL TANK SIDE COVER LH/RH
- 37 GEAR PEDAL
- 38 BRAKE PEDAL
- 39 FRONT FOOT REST LH/RH
- 40 FRONT FOOT REST RUBBER

\$95 ~~X~~ nn
\$650 cut
\$900 bt
\$250 bt
\$90 ner
\$120 Bt
laboar \$580 200? ~~re~~
\$110 cut
\$45 ~~X~~ nn
\$550 dd
\$35 dd
\$40 ~~re~~
\$10 ~~re~~
\$220 dd
\$250 dd
\$120 cut
\$180 cut
\$35 ~~X~~ nn
\$120 bt
\$25 ~~X~~ nn
\$50 cut
\$80 cut
\$12 bt
\$35 brow
\$35 cut
\$120 cut
\$250 cut
\$80 cut
\$90 cut
\$90 cut
\$380 ~~X~~ nn
\$120 ~~X~~ nn
\$45 dd
\$40 cut
\$160 mis
\$360 mis
\$70 bt
\$95 dd
\$180 bt
\$36 fnv

41 FUEL TANK
 42 EXHAUST HEADER+GASKET
 43 EXHAUST MUFFLER COVER
 44 EXHAUST END CAP
 45 REAR SIGNAL LH/RH
 46 REAR WHEEL RIM
 47 TAILBOARD LH/RH
 48 SIDE STAND
 49 MAIN STAND
 50 TOP BOX
 51 TOP BOX BRACKET
 52 LABOUR
 53 TOWING

\$1,150 *del*
 \$980 *del*
 \$90 *del*
 \$120 *del*
 \$120 x *nn*
 \$680 x *nn*
 \$240 x *nn*
 \$60 *del*
 \$90 x *nn*
 \$160 x *nn*
 \$180 x *nn*
 \$900.00 250
 \$30.00

TOTAL AMOUNT:

\$11,553

Tariffi 97445769/67418437

'WP' 18/11/20 @ 5pm

tariffi C/khant.com

5 days

6893

10% - 620370

480

P/P

* Resurvey new parts

668370

20% 5346.96

4 x \$5000

** repair limit

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: