



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0881/2020/NS
DATE : 18-Nov-20
WIP : 57725

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SMA 8246 X

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian,

4 days - ok - Jy - 20 Apr 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR LEE HAN SIANG
ADDRESS : 310B PUNGGOL WALK
#17-554
SINGAPORE 822310
TELEPHONE : HP +65 81012120
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5110900952-01
VEHICLE NO : **SMM 5930 K**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 04/07/2019
ENGINE NO : CHZ C27825
CHASSIS NO : WAUZZZ8V3K1025602
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-Nov-20
PLACE OF ACCIDENT : 528 ANG MO KIO AVE 10 CARPARK

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMM 5930 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	\$ 500.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,000.00	\$ 1,100.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	\$ 240.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 5,282.00	\$ 2,032.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMM 5930 K

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER	\$	1,987.00	
2	FRONT BUMPER FIXING PARTS	\$	185.00	
3	FRONT BUMPER GUIDE SECTION - RH	\$	38.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$	530.00	
5	FRONT BUMPER CLOSING ELEMENT - RH	\$	293.00	
6	FRONT BUMPER COVER TRIM - RH	\$	161.00	
7	WHEEL HOUSING LINER ADAPTER - RH	\$	37.00	
8	FRONT BUMPER AIR GUIDE GRILLE - RH	\$	186.00	
9	FRONT FENDER - RH	\$	841.00	
10	FRONT FENDER ATTACHMENT PARTS	\$	71.00	
11	FRONT FENDER BRACKET - RH	\$	38.00	
12	FRONT FENDER BRACE	\$	95.00	
13	WHEEL HOUSING LINER - RH	\$	167.00	
14	WHEEL HOUSING LINER ATTACHMENT PARTS	\$	88.00	
15	LED HEADLIGHT - RH	\$	5,455.00	
16	LIFT CYLINDER - RH	\$	141.00	
17	FRONT ALUMINIUM RIM - RH		TBC	
18	SUNDRIES	\$	300.00	
TOTAL SPARE PARTS		:	\$ 10,613.00	\$ -
TOTAL LABOUR CHARGES		:	\$ 5,282.00	\$ 2,032.00
GRAND TOTAL		:	\$ 15,895.00	\$ 2,032.00

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT