

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ler, Bernard-JQ

Date: 19 Nov 2020

Preliminary Advice

Vehicle No	: SLL9101C	Accident Date	: 08/11/2020
Make	: AUDI Q5	Policy No.	: 2070125981
Assignment Date	: 18/11/2020	Excess	: S\$0.00
Date of Inspection	: 18/11/2020	Est. Duration of Repair	: 4
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	26,171.00
Revised Amount	:S\$	4,372.00
Check Items (Estimated)	:S\$	300.00
Total	:S\$	4,672.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	205,000.00
COE / PARF Rebate	:S\$	77,728.00
Salvage Value	:S\$	
Margin for Repair	:S\$	127,272.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :