

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0876/2020/TF  
DATE : 17-Nov-20  
WIP : 57811

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

**ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT**

**TEL: 6841 0055 - FAX: 6256 4315**

OWNER'S NAME : WAN SOOK YAN, VALERIE  
ADDRESS : 501 DUUMAN ROAD  
#03-01  
SINGAPORE 97631170  
TELEPHONE : HP +65 9763 1170  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 2070097691  
VEHICLE NO : **SMT 9160 C**  
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI  
MODEL YEAR : 23/7/2020  
ENGINE NO : CHZ C32614  
CHASSIS NO : WAUZZZ8V9KA117751  
MILEAGE :  
DATE IN :  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 13-Nov-20  
PLACE OF ACCIDENT : 501 DUNMAN ROAD

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMT 9160 C**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTER TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	X 280
2	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00	500 ✓
3	TO RSPRAY FRONT BUMPER AND BONNET	\$ 2,000.00	1100 ✓
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 3,522.00</b>	


**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMT 9160 C**

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>Dented</i>		\$ ✓ 1,987.00	✓ 1529.60
2 FRONT BUMPER FIXING PARTS <i>new</i>		\$ 185.00	+x
3 FRONT BUMPER GRILLE - LOWER CTR <i>new</i>		\$ 159.00	+x
4 FRONT BUMPER CLOSING ELEMENT - LOWER <i>new</i>		\$ 530.00	+x
5 FRONT BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	2	\$ 586.00	+x
6 FRONT BUMPER TRIM - LH / RH <i>new</i>	2	\$ 322.00	+x
7 RADIATOR GRILLE <i>lot</i>		\$ ✓ 1,406.00	✓ 1124.60
8 RADIATOR GRILLE CLOSING ELEMENT <i>new</i>		\$ 189.00	+
9 A/C STICKER <i>new</i>		\$ ✓ 8.00	✓ 5.68
10 CAUTION STICKER <i>new</i>		\$ ✓ 14.00	✓ 10.80
11 FRONT BUMPER AIR GRILLE - LH / RH <i>new</i>	2	\$ 372.00	+
12 FRONT BUMPER REINFORCEMENT <i>new</i>		\$ 715.00	+
13 FRONT BUMPER REINFORCEMENT FOAM <i>new</i>		\$ 187.00	+
14 FRONT BUMPER REINFORCEMENT COVER <i>new</i>		\$ 121.00	+
15 FRONT BONNET EDGE PROTECTION <i>new</i>		\$ 28.00	+
16 FRONT BUMPER AIR GUIDE - LH / RH <i>new</i>	2	\$ 48.00	+
17 FRONT BUMPER RADIATOR SUPPORT <i>new</i>		\$ 8.00	+
18 FRONT BUMPER AIR GUIDE - UPPER CENTRE <i>new</i>		\$ 12.00	+
19 FRONT NO. PLATE <i>Dented</i>	S/N	\$ ✓ 60.00	✓ ✓
20 SUNDRIES <i>?</i>		\$ 300.00	? X
<b>TOTAL SPARE PARTS</b>	:	\$ <b>7,237.00</b>	
<b>TOTAL LABOUR CHARGES</b>	:	\$ <b>3,522.00</b>	
<b>GRAND TOTAL</b>	:	\$ <b>10,759.00</b>	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian L  
SURVEYED DATE : 18/11/20  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS : Not Authorised, 04 days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 609H

### Vehicle Details

Vehicle No.: SMT9160C  
Vehicle to be Exported: No  
Intended Deregistration Date: 18 Nov 2020  
Vehicle Make: AUDI  
Vehicle Model: A3 SEDAN 1.0 TFSI S TRONIC (LED)  
Primary Colour: White  
Manufacturing Year: 2019  
Engine No.: CHZC32614  
Chassis No.: WAUZZZ8V9KA117751  
Maximum Power Output: 85.0 kW (113 bhp)  
Open Market Value: \$22,087.00  
Original Registration Date: 23 Jul 2020  
First Registration Date: 23 Jul 2020  
Transfer Count: 0  
Actual ARF Paid: \$22,922.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 22 Jul 2030  
PARF Rebate Amount: \$17,191.00

### Intended COE Rebate Details

COE Expiry Date: 22 Jul 2030  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$32,699.00  
COE Rebate Amount: \$31,644.00  
**Total Rebate Amount: \$48,835.00**

The information contained herein is correct as at 18 Nov 2020

OK





**SIM ONLY**  
**110GB FOR \$35/MTH**

 to 



[Advanced Search](#)

## New Audi A3 Sedan Cars for Sale (1 vehicles)

Sort by Most Popular

15 results/page

Car Model	Price	Dealer	Built in	User Rating
<b>Audi A3 Sedan</b>  1.0 TFSI S tronic (A) Promotion available	<b>\$136,460</b> \$12,500 /yr ?	Premium Automobiles • 21.3km/l   114bhp   7-speed (A) S tronic	<b>Hungary</b>	13 User Reviews

Car Model Price Dealer Built in User Rating

15 results/page

[Home](#) | 
 [New Cars](#) | 
 [Used Cars](#) | 
 [Rental Cars](#) | 
 [Sell My Car](#) | 
 [Directory](#) | 
 [Products](#) | 
 [Insurance](#) | 
 [Article](#) | 
 [Forum](#) | 
 [Resources](#)

sgCarMart is the number one car site for buying Singapore cars, including new cars, parallel import cars & used cars. View all new cars, such as Toyota, Honda, Nissan, Volkswagen, Mitsubishi & BMW. We have new car dealers comprising parallel importers, authorised car distributors, and used car dealers. Find new car pricelists, new car launches, new car promotions, new car reviews, latest car news & car advice. Also join our car discussion and forum discussion for car reviews, motoring news & motoring guides. Visit our partner sites who have job openings for Singapore jobs, Singapore classifieds, mover and real estate.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

**Follow sgCarMart.com**

[About Us](#) | 
 [Careers](#) | 
 [Contact Us](#) | 
 [Sitemap](#) | 
 [Terms of Service](#) | 
 [Privacy Policy](#) | 
 [Personal Data Protection Statement](#)

©2004-2020 sgCarMart, Singapore. All rights reserved.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0876/2020/TF  
DATE : 17-Nov-20  
WIP : 57811

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian,

4 days - ok - Jy - 2 Jan 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : WAN SOOK YAN, VALERIE  
ADDRESS : 501 DUUMAN ROAD  
#03-01  
SINGAPORE 97631170  
TELEPHONE : HP +65 9763 1170  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 2070097691  
VEHICLE NO : SMT 9160 C  
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI  
MODEL YEAR : 23/07/2020  
ENGINE NO : CHZ C32614  
CHASSIS NO : WAUZZZ8V9KA117751  
MILEAGE :  
DATE IN :  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 13-Nov-20  
PLACE OF ACCIDENT : 501 DUNMAN ROAD



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMT 9160 C**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTER TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	\$ 280.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00	\$ 500.00
3	TO RSPRAY FRONT BUMPER AND BONNET	\$ 2,000.00	\$ 1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 3,522.00</b>	<b>\$ 2,072.00</b>




**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMT 9160 C**

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER		\$ 1,987.00	\$ 1,589.60
2 FRONT BUMPER FIXING PARTS		\$ 185.00	
3 FRONT BUMPER GRILLE - LOWER CTR		\$ 159.00	
4 FRONT BUMPER CLOSING ELEMENT - LOWER		\$ 530.00	
5 FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 586.00	
6 FRONT BUMPER TRIM - LH / RH	2	\$ 322.00	
7 RADIATOR GRILLE		\$ 1,406.00	\$ 1,124.80
8 RADIATOR GRILLE CLOSING ELEMENT		\$ 189.00	
9 A/C STICKER		\$ 8.00	\$ 5.68
10 CAUTION STICKER		\$ 14.00	\$ 10.80
11 FRONT BUMPER AIR GRILLE - LH / RH	2	\$ 372.00	
12 FRONT BUMPER REINFORCEMENT		\$ 715.00	
13 FRONT BUMPER REINFORCEMENT FOAM		\$ 187.00	
14 FRONT BUMPER REINFORCEMENT COVER		\$ 121.00	
15 FRONT BONNET EDGE PROTECTION		\$ 28.00	
16 FRONT BUMPER AIR GUIDE - LH / RH	2	\$ 48.00	
17 FRONT BUMPER RADIATOR SUPPORT		\$ 8.00	
18 FRONT BUMPER AIR GUIDE - UPPER CENTRE		\$ 12.00	
19 FRONT NO. PLATE	S/N	\$ 60.00	\$ 60.00
20 SUNDRIES		\$ 300.00	
<b>TOTAL SPARE PARTS</b>	:	<b>\$ 7,237.00</b>	<b>\$ 2,790.88</b>
<b>TOTAL LABOUR CHARGES</b>	:	<b>\$ 3,522.00</b>	<b>\$ 2,072.00</b>
<b>GRAND TOTAL</b>	:	<b>\$ 10,759.00</b>	<b>\$ 4,862.88</b>

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

