

XINYA AUTO SERVICES PTE LTD

11LK 1002 BUKIT ME RAI LANE 3 UNIT # 01 75 SINGAPORE 159719
 E mail : xinyaauto@singnet.com.sg

Date : 12-Nov-20

Address : CHIA ENG HUAT
 BLK
 SINGAPORE 5402

Reference : TP 1262/11/20
 Vehicle No : SMT4428P
 Make/Model : HONDA SHUTTLE
 Insurance Co. : NTUC

RE : SUPPLYMENTRY TO SMT 4428P FOR THIRD PARTY CLAIMS.

<u>PARTS REQUIRED</u>	<u>QTY</u>	<u>COST</u>	<u>AMT \$</u>
FRONT ABSORBER @ \$306.90 EACH	2	613.80	\$961.20 <i>H</i>
ABSORBER MOUNTING	2		\$71.90 <i>bt</i>
LOWER ARM @ \$260 EACH	2	520	\$570.60 <i>bt</i>
LIST PRICE TOTAL		1205.70	\$ 1,603.70
LESS DISCOUNT 20%		964.56	\$ 320.74
LIST PRICE TOTAL AFTER LESS			\$ 1,282.96

NETT PRICE TOTAL

\$0.00

TOTAL PARTS COST

\$1,282.96

LABOUR AND MISCELLANEOUS CHARGES

TO REMOVE & REPLACE UNDERCARRIDGE PARTS
 (LOWER DOWN CROSSMEMBER)

200
 \$ 350.00

LABOUR TOTAL

\$ -

TOTAL ESTIMATED REPAIR COST

\$ 1,412.66

3237
 1520
 964.56
 200
 \$5921.56
 6 DAYS

Profhi
 20/11
 *Permy new parts & old p