



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO20012785/QUqd3q2 Date: 26/01/2021 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLW 4600D	Veh. Inspected	SMV 155S
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2003392/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	20/11/2020
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA NOAH HYBRID	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	ZWR800420962	Colour	BLACK
Odometer	30803 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/11/2020	Inspection Date	05/01/2021
Survey held at	XIN YUN AUTO PTE LTD 1 KAKI BUKIT AVENEU 6 #01-59 AUTOBAY @ KKAI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	