



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO20012789/R1Ktd3q2	
			Date: 08/02/2021	
			Code: SMO	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SJW 1211L
	Policy No.	D20MTPV01002601	Coverage (\$)	0.00
	Claim No.	CMTD2003393/MYE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	20/11/2020
2. Vehicle Particulars & Condition				
	Make & Model	MITSUBISHI LANCER 1.6 GLX A	c.c	1584
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	JMYSRCS3AAU000266	Colour	GREY
	Odometer	144393 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/60 R15	MICHELIN	5 mm
	L/H Front Tyre	195/60 R15	MICHELIN	5 mm
	R/H Rear Tyre	195/60 R15	MICHELIN	5 mm
	L/H Rear Tyre	195/60 R15	MICHELIN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	18/11/2020	Inspection Date	20/11/2020
	Survey held at	ACCORD AUTO SERVICES PTE LTD BLK 1009 BUKIT MERAH LANE 3 #01-80 SINGAPORE 159723		
5a. Remarks				
	A)THE MARKET VALUE IS S\$44,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	