

# ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL:62715133/62717433 FAX:62745715

## ESTIMATE REPAIR

Pg1

Sompo Insurance Singapore Pte Ltd

Vehicle No : SJW1211L

Vehicle Make : Mitsubishi

Claim Type: Own Damage Claim

Vehicle Model : Lancer 1.6 GLX Auto ABS Airbag 2WD 4DR

Chassis No: JMYSRCS3AAU000266

Registration Date : 3 Mar 2010 (Yom:2009) 28 Feb 2030

DOA: 18.11.2020

| No | Description                                                              | Unit        | Cost (\$) |
|----|--------------------------------------------------------------------------|-------------|-----------|
| 1  | FRONT BONNET <i>buc</i>                                                  | 1           | \$ 480.00 |
| 2  | FRONT BONNET HINGE <i>X</i>                                              | 2           | \$ 32.00  |
| 3  | FRONT BONNET STAND <i>X</i>                                              | 1           | \$ 15.00  |
| 4  | FRONT BONNET STAND CLIP <i>X</i>                                         | 1           | \$ 6.00   |
| 5  | FRONT BONNET LOCK <i>bt</i>                                              | 1           | \$ 55.00  |
| 6  | FRONT BONNET INNER LOCK <i>X</i>                                         | 1           | \$ 35.00  |
| 7  | FRONT BONNET SEAL <i>ne</i>                                              | 2           | \$ 18.00  |
| 8  | FRONT BONNET RUBBER <i>ne</i>                                            | 2           | \$ 35.00  |
| 9  | FRONT HEADLAMP LH <i>? cm</i>                                            | 1           | \$ 320.00 |
| 10 | FRONT HEADLAMP RH <i>cm</i>                                              | 1           | \$ 320.00 |
| 11 | FRONT HEADLAMP BRACKET LH <i>? X</i>                                     | 1           | \$ 35.00  |
| 12 | FRONT HEADLAMP BRACKET RH <i>? X</i>                                     | 1           | \$ 35.00  |
| 13 | FRONT FENDER LH <i>repair</i>                                            | 1           | \$ 140.00 |
| 14 | FRONT FENDER RH <i>buc</i>                                               | 1           | \$ 140.00 |
| 15 | FRONT FENDER SHIELD LH & RH <i>LH-X / RH-? X</i>                         | <i>1 pc</i> | \$ 80.00  |
| 16 | FRONT BUMPER <i>de</i>                                                   | 1           | \$ 380.00 |
| 17 | FRONT BUMPER SIDE RETAINER LH & RH <i>LH-<del>8</del> / RH-<i>ne</i></i> | <i>1 pc</i> | \$ 60.00  |
| 18 | FRONT GRILLE BASE <i>scr</i>                                             | 1           | \$ 180.00 |
| 19 | FRONT LOGO <i>ne</i>                                                     | 1           | \$ 50.00  |
| 20 | FRONT GRILLE GARNISH <i>cm</i> / RH / LH- <i>TS</i>                      | 2           | \$ 120.00 |
| 21 | FRONT GRILLE LOWER GARNISH <i>cm</i>                                     | 2           | \$ 70.00  |
| 22 | FRONT FOGLAMP GARNISH <i>RH-<del>7</del> / LH-X</i>                      | 2           | \$ 90.00  |
| 23 | FRONT SUPPORT PANEL <i>H</i>                                             | 1           | \$ 380.00 |
| 24 | FRONT SUPPORT PANEL TOP COVER <i>X</i>                                   | 1           | \$ 220.00 |
| 25 | FRONT AIRDUCT *Support <i>cm</i>                                         | 1           | \$ 38.00  |
| 26 | FRONT REINFORCEMENT BAR <i>bt</i>                                        | 1           | \$ 280.00 |
| 27 | NUMBER PLATE GARNISH <i>bt</i>                                           | 1           | \$ 40.00  |
| 28 | RADIATOR <i>cm</i>                                                       | 1           | \$ 480.00 |
| 29 | AIRCON CONDENDER <i>bt</i>                                               | 1           | \$ 350.00 |

Total (A) : \$ 4,484.00

Cost + 10% : \$ 448.40

Grand Total: \$ 4,932.40

3796  
104  
4175.60

# ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL:62715133/62717433 FAX:62745715

### ESTIMATE REPAIR

Pg 2

Sompo Insurance Singapore Pte Ltd

Vehicle No : SJW1211L

Vehicle Make : Mitsubishi

Claim Type: Own Damage Claim

Vehicle Model : Lancer 1.6 GLX Auto ABS Airbag 2WD 4DR

Chassis No: JMYSRCS3AAU000266

Registration Date : 3 Mar 2010 (Yom:2009) 28 Feb 2030

Chassis No: 18.11.2020

[illegible]

|             |    |        |
|-------------|----|--------|
| Total (B) : | \$ | 590.00 |
|-------------|----|--------|

|              |    |       |
|--------------|----|-------|
| Cost + 10% : | \$ | 59.00 |
|--------------|----|-------|

|              |    |        |
|--------------|----|--------|
| Grand Total: | \$ | 649.00 |
|--------------|----|--------|

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL:62715133/ 62717433 FAX:62745715

Pg 3

Vehicle No : SJW1211L

Vehicle Make : Mitsubishi

Vehicle Model : Lancer 1.6 GLX Auto ABS Airbag 2WD 4DR

Claim Type: Own Damage Claim

Chassis No: JMYSRCS3AAU000266

DOA: 18.11.2020

45-5,200