



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Chua Eng Thai Reg No/Reg Date SLZ1988P / 28/03/201 Date In/Mileage / 56180 Chassis No KNAFZ411MJ5761698 Engine No G4FGHH691693 Make/Model KIA/CERATO K3 1.6 A SX SR Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	20/11/2020/ 13:41	BLE	261 / Edwin Caina	24479

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER, BONNET & FRT SUPPORT PNL REPAIR LHF FENDER, RHF FENDER, LHF A PILLAR & RHF A PILLAR @400x2				800 2800.00
E PNT98000 RESPRAY FRT BUMPER, FRT BUMPER BODY KIT, BONNET, LHF FENDER RHF FENDER, LHF A PILLAR & RHF A PILLAR @350x43				1050 2450.00
E PNT88000 REMOVE & REFIT AC CONDENSER & RADIATOR				? 100.00
M SUNDRY TOP UP AIRCON GAS				? 80.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				40 80.00
M SUNDRY SUPPLY FRT NUMBER PLATE WITH CASING scd				50.00
E PNT88000 REMOVE & REFIT FRT ASSIST PARKING SENSOR				60.00
M SUNDRY Sundries				30.00
COVER-FR BUMPER cm	1.00	633.00	20.00	506.40
CAP-FRONT HOOK xsvl	1.00	9.00	20.00	7.20
MOULDING-FRT BPR LICENSE PLATE ? xsvl	1.00	18.00	20.00	14.40
GRILLE ASSY-RADIATOR cm	1.00	328.00	20.00	262.40
GARNISH-RADIATOR GRILLE,UPR ? bnd	1.00	54.00	20.00	43.20
STRIP ASSY-FR BUMPER UPR ? xsvl	1.00	29.00	20.00	23.20
MOULDING-FRONT BUMPER A/INTAKE ? xsvl	1.00	91.00	20.00	72.80
ABSORBER-FRONT BUMPER ENERGY cm	1.00	84.00	20.00	67.20
STIFFNER-FR BPR LWR ? xsvl	1.00	114.00	20.00	91.20
RAIL ASSY-FR BUMPER ? bt	1.00	496.00	20.00	396.80

confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered or work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing.



g No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<table border="1"> <tr> <td>Cust No/Name</td><td>/Chua Eng Thai</td></tr> <tr> <td>Reg No/Reg Date</td><td>SLZ1988P / 28/03/201</td></tr> <tr> <td>Date In/Mileage</td><td>/ 56180</td></tr> <tr> <td>Chassis No</td><td>KNAFZ411MJ5761698</td></tr> <tr> <td>Engine No</td><td>G4FGHH691693</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO K3 1.6 A SX SR</td></tr> <tr> <td>Colour/Trim</td><td>ABP AURORA BLACK / WK SATURN BLACK</td></tr> </table>	Cust No/Name	/Chua Eng Thai	Reg No/Reg Date	SLZ1988P / 28/03/201	Date In/Mileage	/ 56180	Chassis No	KNAFZ411MJ5761698	Engine No	G4FGHH691693	Make/Model	KIA/CERATO K3 1.6 A SX SR	Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK
Cust No/Name	/Chua Eng Thai														
Reg No/Reg Date	SLZ1988P / 28/03/201														
Date In/Mileage	/ 56180														
Chassis No	KNAFZ411MJ5761698														
Engine No	G4FGHH691693														
Make/Model	KIA/CERATO K3 1.6 A SX SR														
Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	20/11/2020/ 13:41	BLE	261 / Edwin Caina	24479
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M BRACKET-FR BUMPER SIDE MTG, LH <i>? x su</i>		1.00	13.00	20.00	10.40
M BRACKET-FR BUMPER SIDE MTG, RH <i>? x su</i>		1.00	13.00	20.00	10.40
M WIRING HARNESS-FR BUMPER <i>? cut</i>		1.00	237.00	20.00	189.60
M ULTRASONIC SENSOR ASSY-P.A.S <i>AAH (1pc) x su</i>		4.00	177.00	20.00	566.40
M ORNAMENT-KIA NO.115 <i>na</i>		1.00	32.00	20.00	25.60
M NEW K3 AURORA BLACK ABP <i>? x su</i>		1.00	1177.00	00.00	1177.00
M PANEL ASSY-HOOD <i>bt</i>		1.00	1384.00	20.00	1107.20
M HINGE ASSY-HOOD, LH <i>? bt</i>		1.00	34.00	20.00	27.20
M HINGE ASSY-HOOD, RH <i>? bt</i>		1.00	34.00	20.00	27.20
M PAD-HOOD INSULATING <i>x nn</i>		1.00	141.00	20.00	112.80
M LATCH ASSY-HOOD <i>? x su</i>		1.00	65.00	20.00	52.00
M CLIP-HOOD INSULATING PAD MTG <i>na</i>		1.00	1.00	20.00	8.80
M CARRIER ASSY-FRONT END MODULE <i>? ca</i>		1.00	675.00	20.00	540.00
M LAMP ASSY-HEAD, LH <i>x nn</i>		1.00	2209.00	20.00	1767.20
M LAMP ASSY-HEAD, RH <i>sc</i>		1.00	2209.00	20.00	1767.20
M CONDENSER ASSY-COOLER <i>? bt</i>		1.00	681.00	20.00	544.80
M GUARD-AIR, LH <i>? x su</i>		1.00	19.00	20.00	15.20
M GUARD-AIR, RH <i>? ca</i>		1.00	19.00	20.00	15.20
M RADIATOR ASSY <i>? x su</i>		1.00	546.00	20.00	436.80
M BLOWER ASSY <i>? x su</i>		1.00	623.00	20.00	498.40
M RESERVOIR & PUMP ASSY-WASHER <i>? x su</i>		1.00	125.00	20.00	100.00
M COOLANT (4L) <i>? x nn</i>		1.00	26.00	23.00	20.02

SURVEYOR NAME: Zahar - Hp 90010068

SURVEYOR SIGNATURE: [Signature]

DATE: 20/11/2020 @ 1700

REMARKS: 5 days
REJECT / EXCESS : TRA

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

Resurvey before paint

Nett 16,304.22
 7% GST on 16304.22 1141.30

Total Payable 17,445.52

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing rubber seal or other repair requiring the removal of the windscreen.