

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST: 201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD  
190 CLEMENCEAU AVE #03-01  
SINGAPORE SHOPPING CENTRE  
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853  
ATTN: Motor Claim Department

Estimate No: EST2000268  
Date: 20 Nov 2020

Veh Reg No: SKR8645L  
Make/Model: TOYOTA COROLLA  
ALTIS 1.6L CVT  
Chasis No: MR053REH104528494  
Reg. Date: 13/03/2015  
Your Ref No: SME9441X

Claim Type: Third Party  
Accident Date: 20/11/2020  
TP Veh Reg No: SME9441X

*Celine.*

## Estimate Repair Cost to Vehicle No :SKR8645L

| Quantity           | Description                                  | List Price | Amount   |
|--------------------|----------------------------------------------|------------|----------|
|                    |                                              | SS         | SS       |
| <b>List Price</b>  |                                              |            |          |
| 1                  | 1 PC FRT FENDER RH <i>Dented</i>             | 761.50     | ✓        |
| 2                  | 1 PC FRT FENDER COWLING RH <i>torn</i>       | 236.70     | ✓        |
| 3                  | 1 PC FRT FENDER "VVTI" EMBLEM RH <i>new</i>  | 44.30      | ✓        |
| 4                  | 1 PC HEADLAMP RH <i>crushed</i>              | 2,223.20   | ✓        |
| 5                  | 1 PC HEADLAMP BRACKET RH <i>crushed</i>      | 38.20      | ✓        |
| 6                  | 1 PC FRT BUMPER <i>Dislodged</i>             | 458.90     | ✓        |
| 7                  | 1 PC FRT BUMPER REINFORCEMENT <i>Best</i>    | 379.20     | ✓        |
| 8                  | 1 PC FRT BUMPER SPONGE <i>new</i>            | 109.60     | ✓        |
| 9                  | 2 PCS FRT BUMPER BRACKETS <i>new</i>         | 138.20     | x        |
| 10                 | 1 PC FRT BUMPER RETAINER RH <i>new</i>       | 62.90      | ✓        |
| 11                 | 1 PC FRT FOG LAMP RH <i>crushed</i>          | 278.10     | ✓        |
| 12                 | 1 PC FRT FOG LAMP COVER RH <i>crushed</i>    | 93.80      | ✓        |
| 13                 | 1 PC FRT BUMPER GRILLE <i>crushed</i>        | 169.70     | ✓        |
| 14                 | 1 PC FRT GRILLE <i>crushed</i>               | 559.60     | ✓        |
| 15                 | 1 PC FRT GRILLE EMBLEM <i>new</i>            | 69.40      | ✓        |
| 16                 | 1 PC FRT GRILLE RUBBER <i>new</i>            | 76.20      | x        |
| 17                 | 1 PC FRT WIPER TANK <i>new</i>               | 170.40     | ✓        |
| 18                 | 1 PC FRT WIPER TANK MOTOR <i>new</i>         | 228.70     | ✓        |
| 19                 | 1 PC RADIATOR UNDER COVER <i>new</i>         | 185.80     | ✓        |
|                    |                                              | 6,284.40   |          |
| Less 25%           |                                              | 1,571.10   | 4,713.34 |
| <b>Special Net</b> |                                              |            |          |
| 20                 | 1 SET FRT FENDER COWLING CLIPS RH <i>new</i> | 40.00      | 30       |
| 21                 | 1 SET FRT BUMPER CLIPS <i>new</i>            | 60.00      | 30       |
| 22                 | 1 SET FRT BUMPER GRILLE CLIPS <i>new</i>     | 40.00      | 1        |
| 23                 | 1 SET FRT GRILLE TOP COVER CLIPS <i>new</i>  | 40.00      | x        |
| 24                 | 1 SET RADIATOR UNDER COVER CLIPS <i>new</i>  | 40.00      | 20       |
|                    |                                              | 220.00     | 220.00   |

5841.30

4380.97

80

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD  
190 CLEMENCEAU AVE #03-01  
SINGAPORE SHOPPING CENTRE  
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853  
ATTN: Motor Claim Department

Estimate No: EST2000268

Date: 20 Nov 2020

Veh Reg No: SKR8645L

Make/Model: TOYOTA COROLLA  
ALTIS 1.6L CVT

Chasis No: MR053REH104528494

Reg. Date: 13/03/2015

Your Ref No: SME9441X

Claim Type: Third Party  
Accident Date: 20/11/2020  
TP Veh Reg No: SME9441X

## Estimate Repair Cost to Vehicle No :SKR8645L


| Quantity | Description                                                                                                   | List Price | Amount              |
|----------|---------------------------------------------------------------------------------------------------------------|------------|---------------------|
|          |                                                                                                               | <u>S\$</u> | <u>S\$</u>          |
|          | <b>Labour</b>                                                                                                 |            |                     |
| 25       | 1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS. | 1,000.00   | 600                 |
| 26       | 1 TO SPRAY PAINTING                                                                                           | 1,000.00   | 800                 |
| 27       | 1 TO SPRAY UNDERSEAL                                                                                          | 80.00      | 30                  |
| 28       | 1 TO CHECK WIRING                                                                                             | 50.00      | 30                  |
|          |                                                                                                               | 2,130.00   | 2,130.00            |
|          | Total                                                                                                         |            | S\$ 7,063.34        |
|          | Add GST @ 7%                                                                                                  |            | 494.43              |
|          | Total Amount Payable                                                                                          |            | <u>S\$ 7,557.77</u> |

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND FIVE HUNDRED FIFTY SEVEN AND CENTS SEVENTY SEVEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

AT

For Kang Car Repairers Pte Ltd

  
AUTHORISED SIGNATURE

Admin  total: \$92097  
h/s 23/11/20 L/S: 4.7K.  
05 days. 4.7K