



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO20012835/BKtf3e2 Date: 13/01/2021 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBH 3556C	Veh. Inspected	GBC 4790L
Policy No.	D20MTPCVE001314	Coverage (\$)	0.00
Claim No.	CMTD2003405/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	23/11/2020
2. Vehicle Particulars & Condition			
Make & Model	NISSAN CABSTAR 3.0	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	JN1SC2F24Z0850361	Colour	BLUE
Odometer	414309 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	APLUS	5 mm
L/H Front Tyre	195 R15	APLUS	5 mm
R/H Rear Tyre	165 R13	LUXOTIK	5 mm
L/H Rear Tyre	165 R13	LUXOTIK	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/11/2020	Inspection Date	23/11/2020
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	