Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way

#09-16

Singapore 079120

LKK Auto Consultants Pte Ltd From:

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Nadaraja, Deeban Date: 24 Nov 2020

Preliminary Advice

Vehicle No : SDL186L Accident Date : 17/11/2020 : AUDI A3 Policy No. : 2070054898 Make Assignment Date : 23/11/2020 **Excess** : S\$0.00 Date of Inspection : 23/11/2020 Est. Duration of Repair : 4

: PREMIUM AUTOMOBILES PTE LTD (UBI) Inspection At

> 55 UBI ROAD 1 SINGAPORE 408699

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,469.00
Revised Amount	:S\$	6,865.00
Check Items (Estimated)	:S\$	509.00
Total	:S\$	7,374.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	140,000.00
COE / PARF Rebate	:S\$	56,395.00
Salvage Value	:S\$	
Margin for Repair	:S\$	83,605.00

Remarks

(X	()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :