

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina

Date: 24 Nov 2020

Preliminary Advice

Vehicle No	: SLP7848Z	Accident Date	: 23/11/2020
Make	: MITSUBISHI LANCER	Policy No.	: 1700018373
Assignment Date	: 23/11/2020	Excess	: S\$0.00
Date of Inspection	: 23/11/2020	Est. Duration of Repair	: 8
Inspection At	: CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,719.76
Revised Amount	:S\$	8,069.64
Check Items (Estimated)	:S\$	2,550.36
Total	:S\$	10,620.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	55,000.00
COE / PARF Rebate	:S\$	39,912.00
Salvage Value	:S\$	
Margin for Repair	:S\$	15,088.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :