

Surveyor : TAUFIKH LKK
 Claim : AIG OD
 DOA : 23.11.2020
 Emailed : 17.12.2020, 4.15pm
 Date Survey : 23.11.2020

VEHICLE NO : SLP 7848 Z
 MODEL : MIT LANCER EX 1.6 A
 WIP : 59871

Material	:	\$	<u>5,656.42</u>
Labour	:	\$	<u>5,260.00</u>
Sub-Total	:	\$	<u>10,916.42</u>
	:		<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>10,916.42</u>
GST 7%	:	\$	<u>764.15</u>
Grand Total	:	\$	<u>11,680.57</u>
Finalise By/Date	:		<u>LOI / 17/12/2020</u>

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 24/11/2020	<table> <tr><td>Cust No/Name</td><td>KCV17673/Ting Kay Chong</td></tr> <tr><td>Reg No/Reg Date</td><td>SLP7848Z / 19/06/2017</td></tr> <tr><td>Date In/Mileage</td><td>23/11/2020/ 48691</td></tr> <tr><td>Chassis/Package</td><td>JMYSRCY1AGU006783 /DC17S3C</td></tr> <tr><td>Engine No</td><td>4A92CP4458</td></tr> <tr><td>Make/Model</td><td>MIT/16MY LANCER EX 1.6 4AT (E21)</td></tr> <tr><td>Colour/Trim</td><td>DOO LIGHTNING BLUE / BK BLACK</td></tr> </table>	Cust No/Name	KCV17673/Ting Kay Chong	Reg No/Reg Date	SLP7848Z / 19/06/2017	Date In/Mileage	23/11/2020/ 48691	Chassis/Package	JMYSRCY1AGU006783 /DC17S3C	Engine No	4A92CP4458	Make/Model	MIT/16MY LANCER EX 1.6 4AT (E21)	Colour/Trim	DOO LIGHTNING BLUE / BK BLACK
Cust No/Name	KCV17673/Ting Kay Chong														
Reg No/Reg Date	SLP7848Z / 19/06/2017														
Date In/Mileage	23/11/2020/ 48691														
Chassis/Package	JMYSRCY1AGU006783 /DC17S3C														
Engine No	4A92CP4458														
Make/Model	MIT/16MY LANCER EX 1.6 4AT (E21)														
Colour/Trim	DOO LIGHTNING BLUE / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	17/12/2020/ 12:31	BLK	260 / AiTing	59871			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE RH FRONT FENDER, BONNET, FRONT BUMPER, REPAIR LH FRONT FENDER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 1800.00
E PNT98000 RESPRAY ON FRONT BUMPER, BONNET, BOTH FRONT FENDER, LH FRONT DOOR, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 1750.00
E PNT88000 REMOVE & INSTALL RADIATOR, & A/COND CONDENSER TO FACILITATE REPAIR								? 120.00
M SUNDRY VACUUM & TOP UP A/COND GAS								? 80.00
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS								✓ 40.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE								✓ 120.00
M SUNDRY SUNDRIES								✓ 20.00
S SPECIALISTJOB SUPPLY & REPLACE FRONT NUMBER PLATE WITH FRAME								✓ 50.00
E PNT88000 REPLACE FRONT SUPPORT PANEL & REPAIR BOTH FRONT CHASSIS → Supp.								900.00
E PNT98000 RESPRAY FRONT SUPPORT PANEL & REPAIR BOTH FRONT CHASSIS → Supp.								350.00
X					1.00	? 846.00	23.00	651.42
X					1.00	✓ 846.00	23.00	651.42
X					1.00	✓ 607.00	23.00	467.39
X					1.00	✓ 93.00	23.00	71.61
X					1.00	✓ 1040.00	23.00	800.80
X					1.00	✓ 529.00	23.00	407.33
X					1.00	✓ 268.00	23.00	206.36
X					1.00	✓ 78.00	23.00	60.06

PRO-FORMA INVOICE

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 24/11/2020	<table> <tr><td>Cust No/Name</td><td>KCV17673/Ting Kay Chong</td></tr> <tr><td>Reg No/Reg Date</td><td>SLP7848Z / 19/06/2017</td></tr> <tr><td>Date In/Mileage</td><td>23/11/2020/ 48691</td></tr> <tr><td>Chassis/Package</td><td>JMYSRCY1AGU006783 /DC17S3C</td></tr> <tr><td>Engine No</td><td>4A92CP4458</td></tr> <tr><td>Make/Model</td><td>MIT/16MY LANCER EX 1.6 4AT (E21)</td></tr> <tr><td>Colour/Trim</td><td>DOO LIGHTNING BLUE / BK BLACK</td></tr> </table>	Cust No/Name	KCV17673/Ting Kay Chong	Reg No/Reg Date	SLP7848Z / 19/06/2017	Date In/Mileage	23/11/2020/ 48691	Chassis/Package	JMYSRCY1AGU006783 /DC17S3C	Engine No	4A92CP4458	Make/Model	MIT/16MY LANCER EX 1.6 4AT (E21)	Colour/Trim	DOO LIGHTNING BLUE / BK BLACK
Cust No/Name	KCV17673/Ting Kay Chong														
Reg No/Reg Date	SLP7848Z / 19/06/2017														
Date In/Mileage	23/11/2020/ 48691														
Chassis/Package	JMYSRCY1AGU006783 /DC17S3C														
Engine No	4A92CP4458														
Make/Model	MIT/16MY LANCER EX 1.6 4AT (E21)														
Colour/Trim	DOO LIGHTNING BLUE / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	17/12/2020/ 12:31	BLK	260 / AiTing	59871		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
X	COVER,HEADLAMP SUPT PANEL			1.00	?	70.00 23.00	53.90
X	SUPPORT,FR BUMPER,RH			1.00	✓	13.00 23.00	10.01
X	BRACKET,FR BUMPER SIDE,RH			1.00	✓	17.00 23.00	13.09
X	MARK,THREE-DIA			1.00	✓	69.00 23.00	53.13
X	COVER,FR BUMPER			1.00	✓	38.00 23.00	29.26
X	HOOD			1.00	✓	913.00 23.00	703.01
X	HINGE,HOOD,LH			1.00	✓	64.00 23.00	49.28
X	HINGE,HOOD,RH			1.00	✓	64.00 23.00	49.28
X	FENDER,FR RH			1.00	✓	688.00 23.00	529.76
X	PNL,HEADLAMP SUPT,UPR RH			1.00	✓	86.00 23.00	66.22
X	SHIELD,FR FENDER,FR RH			1.00	✓	119.00 23.00	91.63
X	TANK,WINDSHIELD WASHER			1.00	✓	90.00 23.00	69.30
X	GROMMET,HEADLAMP			1.00	✓	3.00 23.00	2.31
X	PANEL,HEADLAMP SUPPORT,UPR			1.00	?	296.00 23.00	227.92
X	COVER,FR BUMPER GRILLE			1.00	?	5.00 23.00	3.85
X	GARNISH,FR BUMPER,RH			1.00		37.00 23.00	28.49
X	COVER,ENG ROOM UNDER,FR			1.00		173.00 23.00	133.21
X	GARNISH,FR BUMPER,CTR			1.00	?	234.00 23.00	180.18
X	CLIP,RR BUMPER			20.00		3.00 23.00	46.20
Z	TEXT						
	AIG OD CLAIM.						
	DOA : 23.11.20						
	SURVEYOR TAUFIKH LKK 23.11.20						
	POLICY NO : 1700018373-03						

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	5,656.42	Nett	10,916.42
Labour	5,070.00	7% GST on	764.15
Standard Menu	0.00		
Specialist Job	50.00		
Diagnostics Job	0.00		
Sundry/Others	140.00		
Total(w/o GST)	10,916.42	Total Payable	11,680.57



Exceptional Journeys

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SLP 7848 Z

<u>Materials</u>		<u>Cost (\$)</u>
1	Tank, windshield washer	90.00
2	Grommet	3.00
3	Cover, Fr bumper grille	5.00
4	Garnish, Fr bumper, RH	37.00
5	Cover, Eng room under, Fr	173.00
6	Glip (x20)	60.00

Total		368.00
Less 23%		84.64

Total Materials		283.36

<u>Labour</u>		<u>Cost (\$)</u>
1	Replace front support panel & repair both front chassis	900.00
2	Respray front support panel & repair both front chassis	350.00


Total Labour		1,250.00

Taxable Amount		1,533.36
7% GST		107.34

Grand total		<u><u>1,640.70</u></u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD



LOI AI TING
SENIOR OFFICER - ADMIN
TEL: 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

SLP7848Z

3876 using MOT-3x

not wit to check all the sand
bad Base all the sand
to Job Done

2020.12.04

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20011-00
V.C.I. Version	B177
Vehicle Information	CY1A 2016MY

212