



# 南方摩哆 Southern Motor

Business Reg. No: 234147/00L  
Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762  
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

20<sup>th</sup> November 2020  
AIG Asia Pacific Insurance Pte Ltd  
78 Shanton Way #07-16  
AIG Building  
Singapore (079120)

Dear Sirs,

**RE: Cost of repair to Kawasaki ZX150-149CC – FV1830C**

|                                          |                |                         |
|------------------------------------------|----------------|-------------------------|
| 1pc of Front Fairing <i>SCA</i> ✓        | S\$            | 285.00                  |
| 1pc of Front Mudguard <i>SCA</i> ✓       |                | 98.00                   |
| 2pc of Front Signal RH/LH <i>MIS</i> ✓   |                | 70.00                   |
| 1pc of Front Brake Disc ?                |                | 225.00                  |
| 1pc of Brake Shoe Pump ?                 |                | 265.00                  |
| 1pc of Brake Pedal <i>bt</i> ✓           |                | 75.00                   |
| 1pc of Brake Lever <i>SCA</i> ✓          |                | 18.00                   |
| 1pc of Front Fairing Bracket <i>bt</i> ✓ |                | 185.00                  |
| 1pc of Handle Bar <i>bt</i> ✓            |                | 90.00                   |
| 1pc of Air Pipe Cover ?                  |                | 48.00                   |
| 1pc of Rear Side Box <i>X</i> NN         |                | 260.00                  |
| 1pc of Exhaust Pipe <i>SCA</i> ✓         |                | 190.00                  |
|                                          |                | <hr/> 1,809.00          |
|                                          | Less 10%       | 180.90                  |
|                                          | Nett           | 1,628.10                |
|                                          | Transport      | 30.00                   |
|                                          | Alignment Fork | 75.00                   |
|                                          | Labor          | 200.00                  |
|                                          |                | <hr/> <u>\$1,933.10</u> |



Yours Faithfully,  
Southern Motor

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Ranu*  
*Hp 9001068*  
*3 days*  
*4/3*  
*28/11/2020 @ 1100*  
*Resy after repair*