

FASTECH AUTO PTE LTD

page 1/2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Estimate : 19031

Date : 14.12.2016

Vehicle Num : WQV 3222

Make/Model : TOYOTA CAMRY

Chassis/Engine no :

Accident Date : 24.09.2016

Claim No :

Reference :

Policy No :

Qty	Particular	Amount S\$
-----	------------	------------

List Item

1 pc	Rear boot lid	929.10
1 pc	Rear boot lock	429.10
1 pc	Rear boot lock catch	
1 pc	Rear boot centre garnish	
1 pc	Rear boot centre emblem	48.50
2 pc	Rear boot absorber @	256.50
1 pc	Rear boot inner garnish	
1 pc	Rear boot emblem (camry)	
1 pc	Rear boot emblem (2.0)	
1 pc	Rear boot 'C7' emblem	42.10
2 pc	Rear boot reflector lamp @	499.40
2 pc	Rear boot hinge @	121.90
1 pc	Rear boot rubber weatherstrip	
2 pc	Rear boot number plate lamp @	56.70
2 pc	Rear tail lamp @	595.70
2 pc	Rear tail lamp lower bracket @	25.20
1 pc	Rear end panel	
1 pc	Rear end panel top garnish	
1 pc	Rear bumper	525.10
2 pc	Rear bumper side retainer @	103.10
1 pc	Rear bumper towing cover	
1 pc	Rear bumper reinforment	399.20
1 pc	Rear exhaust silencer	
2 pc	Rear exhaust rubber @	60.80
2 pc	Rear fender @	1263.00
2 pc	Rear fender inner garnish @	434.30
1 pc	Rear spare tyre panel	
1 pc	Rear spare tyre panel top cover board	
1 pc	Rear glass mldg	
List Item Total :		
Discount 25 %		

sent/\$	1,253.20	✓
\$	892.20	✓
\$	51.80	X
\$	393.80	X
\$	77.40	✓
\$	513.00	X
\$	499.80	X
\$	58.50	✓
\$	48.20	✓
\$	77.40	✓
\$	998.80	X
\$	243.80	X
\$	207.30	✓
\$	113.40	X
Days/\$	1,291.40	✓
\$	50.40	X
\$	895.60	✓
\$	421.30	✓
\$	915.20	✓
\$	206.20	X
\$	26.50	X
\$	561.30	✓
sent/\$	981.30	✓
\$	121.60	✓
\$	2,526.00	X
\$	868.60	X
\$	1,051.50	X
\$	396.60	✓
\$	185.30	X
\$	15,927.40	
\$	3,981.85	
\$	11,945.55	

6794.9
5096.11

FASTECH AUTO PTE LTD

page 2/2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Estimate : 19031

Date : 14.12.2016

Vehicle Num : WQV 3222

Make/Model : TOYOTA CAMRY

Chassis/Engine no :

Accident Date : 24.09.2016

Claim No :

Reference :

Policy No :

Qty	Particular	Amount S\$
	B / F \$	11,945.55
<u>Special Nett Item :</u>		
4 pc	Rear tail lamp clips @ 6.50	\$ 11 26.00 X
12pc	Rear fender inner garnish clips @ 6.50	\$ 11 78.00 X
12pc	Rear boot inner board clips @ 6.50	\$ 11 78.00 X
1 pc	Rear spare tyre panel top insulator	\$ 11 250.00 X
1 pc	Rear end panel sealant	\$ 22 100.00 50
1 pc	Rear number plate	\$ 11 45.00 X
1 pc	Rear glass sealant	\$ 11 100.00 X
1 set	Rear bumper reverse sensor	\$ sub 350.00 200
Special Nett Total :		\$ 1,027.00
<u>Labour Charge :</u>		
	To check wiring	\$ 180.00 -20
	Tuff kote	\$ 180.00 -60
	Towing	\$ 11 80.00 X
	Remove and refix upholstery	\$ 160.00 60
	Remove and replace exhaust pipe	\$ 160.00 60
	Remove and replace reverse sensor	\$ 160.00 50
	Remove and refix rear glass	\$ 11 160.00 X
	To remove and replace spare part and panel beating	\$ 1,800.00 800
	To spray painting and etc	\$ 1,800.00 1200
Labour Charge Total :		\$ 4,680.00

7586.17

6076

Singdollars :Seventeen Thousand Six Hundred Fifty Two And Cents Fifty Five Only .

E & O . E

Total Amount : \$ 17,652.55

FASTECH AUTO PTE LTD