



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

6 Benoi Place Singapore 629927

Tel: 6861 0908 Fax: 6515 2948

Date: 23.11.2020

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01

NTUC Trade Union House

Singapore 189556

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SLW3996T TOYOTA PRIUS ALPHA 1.8 HYBRID (2018)

To Supply

1) 1pc	Front bumper	\$	585.00 <i>den</i>
2) 1pc	Front bumper left side retainer	\$	65.70 <i>nn</i>

Sub total parts	\$	650.70 <i>585.00</i>
Less: 25% discount	\$	162.67 <i>-146.25</i>
	\$	488.03 <i>438.75</i>

To supply S.Nett Parts

1) 1set	Front bumper clips	\$	30.00 <i>re</i>
----------	--------------------	----	-----------------

Sub total S.Nett Parts	\$	30.00 <i>✓</i>
------------------------	----	----------------

L/charges

1) To repair left front fender. Remove front bumper. Replace the above necessary parts. Align & adjust front bumper.	\$	400.00 <i>250</i>
2) To putty, respray painting front bumper & left front fender. To polish.	\$	500.00 <i>400</i>

Sub total L/charges	\$	900.00 <i>650.00</i>
Estimated Grand Total	\$	1,418.03 <i>1118.75</i>
		<i>less: 25% 4/5 - 223.75</i>
		<i>895.00</i>

Tanpin 97495749
WP' 24/11/2020 3pm
Comp 500
Respray after repair
2 days

l/s\$900, 2 days