



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota M account & more!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188
Customer Detail

Account Detail	Account No	
THIRD PARTY CLAIM	S1000020 / TPCLAIM	
	Document No	Mr See Kay Choong 62 Keris Drive Singapore 457012 Mobile: 92359835
	Document Date	0
		23/11/2020

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	S2	ZRE171R	23/06/2015	SKT7904K	0	58257 65/OD/SKT7904K
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR053REH104535267	12RX519261	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-MS SUNDRIES POLICY NO.: A 29083646 ATE ACC DATE: 20.11.20 TOW IN : 20.11.20 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				30. 50.00
2	L	BP-LPO SUPPLY REGN PLATE (PO#)				dd 80.00
3	Z	BP-SLANT SUPPLY SEALANT (NETT)				rel 100.00
4	S	BP-SUBLET RESET AND REPROGRAMME ECU.				180.00
5	B	BP-LAB2 REPLACE AND REFOCUS HEADLAMP.				180.00
6	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN FRT BUMPER, BONNET, R/F FENDER AND AFFECTED PORTION OF CAR.				2160. 2880.00
7	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				1770. 2360.00
8	1	S53301-02310 HOOD SUB-ASSY	1.00	1248.80		bt 1248.80
9	2	S53100-02760 GRILLE, RADIATOR	1.00	643.00		cr 643.00
10	3	S53801-02240 FENDER SUB-ASSY, RH	1.00	908.70		bt 908.70
11	4	S75444-02700 PLATE, LUGGAGE COMPT	1.00	35.50		rel 35.50

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Tan Jiah 97495749 WP 24/11/20 0445pm Less 6 days Resurvey before paint Amount Due Tan Jiah @ kharpa.com
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		4381810 4381810

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

Acknowledged by Repairer
Signature: 23/11/2020
Date: 10:54

VEHICLE NO

SKT7904K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188
Customer Detail

Account Detail	Account No	
THIRD PARTY CLAIM	Document No	Mr See Kay Cheong 62 Keris Drive Singapore 457012 Mobile: 92359835
	Document Date	
	23/11/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	S2	23/06/2015	SKT7904K	0	58257	65/OD/SKT7904K
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR053REH104535267	12RX519261	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	5	S52115-02270 SUPPORT, FR BUMPER RH	1.00	85.50		nn X 85.50
13	6	S81110-02F51 HEADLAMP ASSY, RH	1.00	2999.80		ca ✓ 2999.80
14	7	S81150-02F51 HEADLAMP ASSY, LH	1.00	2999.80		nn X 2999.80
15	8	S55701-02420 PANEL SUB-ASSY, COWL	1.00	429.40		45 ✓ 429.40
16	9	S11212-0T120 COVER, CYLINDER HEAD	1.00	410.50		an ✓ 410.50
17	0	S53341-02290 INSULATOR, HOOD	1.00	280.10		de ✓ 280.10
18	1	S53410-02360 HINGE ASSY, HOOD RH	1.00	58.90		bt ✓ 58.90
19	2	S53420-02360 HINGE ASSY, HOOD, LH	1.00	58.90		nn X 58.90

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	15,988.90
		Labour 10,158.90	GST 7.00%
		Materials 5,570.00	Less
		Lubrication/Fluid 260.00	0.00
		Others 0.00	Amount Due
		0.00	17,108.12

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 23/11/2020
TIME 10:54

VEHICLE NO

SKT7904K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

4381811

4381811